Tetra Tech EM Inc.



Northmont Business Park ♦ 1955 Evergreen Boulevard, Building 200, Suite 300 ♦ Duluth, GA 30096 ♦ (678) 775-3080 ♦ FAX (678) 775-3138

September 10, 2001

Ms. Amy Williams Remedial Project Manager U.S. Environmental Protection Agency, Region 4 61 Forsyth Street, SW 11th Floor Atlanta Georgia 30303

SEP 1 2 2001

EPA-REGION 4 ATLANTA, GA

Subject:

Final Expanded Site Inspection Report

Jordan Sign Company

EPA Contract No. 68-W-00-120 EPA ID No. GAD003293057

Technical Direction Document No. 4T-01-10-A-007

Dear Ms. Williams:

The Tetra Tech EM Inc. Superfund Technical Assessment and Response Team (START) is submitting one copy of the final expanded site inspection (ESI) report for the Jordan Sign Company in Savannah, Chatham County, Georgia. Per our conversation today, EPA Region 4 has reviewed the draft ESI report dated September 4, 2001, and has no comments on the draft ESI report. Due to your acceptance of the draft ESI report, Tetra Tech EM Inc., is submitting only the cover page for the final report.

If you have any questions or comments regarding this submittal, please contact me at (678) 775-3081.

Sincerely,

David L. Brown

START Project Manager

Enclosure

cc:

Matthew Monsees, EPA Project Officer (w/o enclosures)

Cindy Gurley, EPA Process Owner (w/o enclosures)

Steve Pierce, START Leader (w/o enclosures)

Paul Moisan, START Site Assessment Coordinator (w/o enclosures)

START File

FINAL EXPANDED SITE INSPECTION REPORT

JORDAN SIGN COMPANY SAVANNAH, CHATHAM COUNTY, GEORGIA

US EPA ID NO. GAD003293057

Revision 1

Prepared for

U.S. ENVIRONMENTAL PROTECTION AGENCY Region 4 Atlanta, Georgia 30303

Contract No. 68-W-00-120 TDD No. 4T-01-10-A-007 Date Prepared September 10, 2001 Amy Williams (404) 562-8776 EPA Task Monitor Telephone No. Tetra Tech EM Inc. Prepared by START Project Manager David L. Brown Telephone No. (678) 775-3081

Prepared by

David L. Brown

START Project Manager

Reviewed by

Approved by

Sandra J. Harrigan

START Technical Reviewer

R. Steve Pierce START Leader

FINAL EXPANDED SITE INSPECTION REPORT

JORDAN SIGN COMPANY SAVANNAH, CHATHAM COUNTY, GEORGIA

US EPA ID NO. GAD003293057

Revision 1

Prepared for

U.S. ENVIRONMENTAL PROTECTION AGENCY Region 4 Atlanta, Georgia 30303

Contract No. TDD No. Date Prepared **EPA Task Monitor** Telephone No. Prepared by

START Project Manager Telephone No.

68-W-00-120 4T-01-10-A-007

September 10, 2001 Amy Williams (404) 562-8776 Tetra Tech EM Inc.

David L. Brown (678) 775-3081

Prepared by

David L. Brown

START Project Manager

Reviewed by

Approved by

R. Steve Pierce START Leader

CONTENTS

1.0	INTRODU	CTION 1
2.0	SITE BAC	KGROUND 2
	2.1 2.2 2.3 2.4	SITE DESCRIPTION AND ENVIRONMENTAL SETTING 2 SITE OPERATIONS AND REGULATORY HISTORY 5 PREVIOUS RELEASES AND INVESTIGATIONS 5 POTENTIAL SOURCE AREAS 6
3.0	ESI ACTI	'ITIES 6
	3.1 3.2 3.3	SAMPLE COLLECTION METHODOLOGY AND PROCEDURES 7 ANALYTICAL SUPPORT AND METHODOLOGY 7 ANALYTICAL DATA QUALITY AND DATA QUALIFIERS 7
4.0	SOURCE	SAMPLING
	4.1 4.2	SOURCE SAMPLE LOCATIONS AND ANALYTICAL RESULTS
5.0	PATHWA	'S 24
	5.1	GROUNDWATER MIGRATION PATHWAY 24
		5.1.1Geologic and Hydrogeologic Setting245.1.2Groundwater Sampling Locations and Analytical Results265.1.3Groundwater Targets275.1.4Groundwater Conclusions33
	5.2,	SURFACE WATER MIGRATION PATHWAY
		5.2.1Hydrologic Setting
	5.3	SOIL EXPOSURE PATHWAY AND AIR MIGRATION PATHWAY 41
		5.3.1 Physical Conditions415.3.2 Soil and Air Sample Locations and Analytical Results415.3.3 Soil and Air Targets415.3.4 Soil and Air Conclusions42
6.0	SUMMAR	Y AND CONCLUSIONS 42
REF	ERENCES	

CONTENTS (Continued)

					٠	
А	n	pe	n	d	1	X

Å	ANALYTICAL DATA SET
В	PHOTOGRAPH LOG

T.I	$\boldsymbol{\sim}$	T	ID	Tr.	c
г	١×		JIK	r.	•

Fig	<u>ure</u> Pa	ige
1	GENERAL SITE MAP	. 3
2	SITE LAYOUT MAP	4
3	SAMPLING LOCATION MAP	8
× .	TABLES	
Tab	<u>Pa</u>	age
1	SURFACE SOIL SAMPLING LOCATIONS AND RATIONALE	9
2	SUBSURFACE SOIL SAMPLING LOCATIONS AND RATIONALE	10
3	GROUNDWATER SAMPLING LOCATIONS AND RATIONALE	11
4	SURFACE WATER SAMPLING LOCATIONS AND RATIONALE	13
5	SEDIMENT SAMPLING LOCATIONS AND RATIONALE	14
6	SUMMARY OF INORGANIC ANALYTICAL RESULTS - SURFACE SOIL SAMPLES	18
7	SUMMARY OF ORGANIC ANALYTICAL RESULTS - SURFACE SOIL SAMPLES	19
8	SUMMARY OF INORGANIC ANALYTICAL RESULTS - SUBSURFACE SOIL SAMPLES .	21
9	SUMMARY OF ORGANIC ANALYTICAL RESULTS - SUBSURFACE SOIL SAMPLES	22
10	SUMMARY OF FIELD PARAMETERS - GROUNDWATER SAMPLES	28
11	SUMMARY OF INORGANIC ANALYTICAL RESULTS - PRIVATE AND MUNICIPAL WELLS	29
12	SUMMARY OF INORGANIC ANALYTICAL RESULTS - GROUNDWATER SAMPLES	30
13	SUMMARY OF ORGANIC ANALYTICAL RESULTS - GROUNDWATER SAMPLES	31
14	FLORIDAN AQUIFER - DRINKING WATER WELLS AND POPULATION SERVED	32
15	SUMMARY OF INORGANIC ANALYTICAL RESULTS - SURFACE WATER SAMPLES	36
16	SUMMARY OF ORGANIC ANALYTICAL RESULTS - SURFACE WATER SAMPLES	37

CONTENTS (Continuted)

<u>Tab</u>	<u>ble</u>	Page.	
17	SUMMARY OF INORGANIC ANALYTICAL RESULTS - SEDIMENT SAMPLES .		38
18	SUMMARY OF ORGANIC ANALYTICAL RESULTS - SEDIMENT SAMPLES		39

1.0 INTRODUCTION

The U.S. Environmental Protection Agency (EPA) directed the Tetra Tech EM Inc. (Tetra Tech) Superfund Technical Assessment and Response Team (START) to conduct an expanded site inspection (ESI) at the Jordan Sign Company, EPA ID No. GAD003293057, under Contract No. 68-W-0021, Technical Direction Document No. 04-9902-0005. The ESI was completed under Contract No. 68-W-00-120, TDD No. 4T-01-10-A-007.

The primary objective of an ESI is to determine whether a facility has the potential to be placed on the National Priorities List (NPL). The NPL identifies facilities at which a release, or threatened release, of hazardous substances poses a risk to public health or the environment sufficient to warrant further investigation and possible remediation under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) of 1980 and the Superfund Amendments and Reauthorization Act of 1986.

Information gathered during the ESI is used to generate a preliminary Hazard Ranking System (HRS) score. The HRS score is the primary criterion EPA uses to determine whether a facility should be placed on the NPL. ESIs are generally conducted at facilities where additional environmental sampling or monitoring well installation is necessary to fulfill HRS documentation requirements. ESIs are also conducted to address issues not adequately resolved through previous investigations.

Specifically, the objectives of the ESI are as follows:

- Obtain and review relevant file material
- Collect samples to determine whether hazardous substances are attributable to facility operations
- Collect samples to establish representative background levels
- Evaluate target populations for the groundwater migration, surface water migration, soil exposure, and air migration pathways
- Collect any other data necessary to derive an HRS score
- Document current facility conditions
- Develop a facility layout map

This report documents the results of the ESI conducted at the facility during the week of March 26, 2001. Information reviewed for the ESI was gathered from EPA Region 4 CERCLA files.

2.0 SITE BACKGROUND

This section describes the facility, its present and past operations (including waste disposal practices and regulatory history), previous investigations, and potential source areas located at the facility.


2.1 SITE DESCRIPTION AND ENVIRONMENTAL SETTING

The Jordan Sign Company property is an inactive landfill located on the East President Street Extension in Savannah, Chatham County, Georgia. The geographical coordinates are latitude 32° 31' 28.0" N and longitude 89° 41' 23.0" W (see Figure 1) (Refs. 1; 2, pp. 1, 3; 3; 4; 5; 6, p. 23). The property is currently owned by Southern States Phosphate and Fertilizer Company (Refs. 7; 8; 9; 10). The landfill which is located on 24.38 acres of land, was used for the disposal of construction debris and dredge spoils sometime after the early 1960s until sometime prior to 1977. In 1979, it was reported that Hercules, Inc., had disposed of resin waste at the landfill. No further information is available in the site files concerning the types and quantities of waste deposited at the landfill (Refs. 2; 4; 5; 7; 8; 9; 10).

The land use of area surrounding the landfill is commercial and industrial. An apiary is currently located on the central portion of the landfill property, and a spoil disposal area is located on the southern portion of the property. The Southern States Phosphate and Fertilizer facility is located adjacent to the east-northeast portion of the landfill. Ind Chem, Inc., is located adjacent to the southeast corner of the landfill. The Savannah Country Club and golf course is located immediately southeast of the landfill across the East President Street Extension. Dulany Road borders the landfill property on both the west and north boundary. Located west of Dulany Road is a wooded area situated on the east bank of the Kayton Canal. The City of Savannah President Street Wastewater Treatment facility is located adjacent to the west bank of the Kayton Canal. The area directly south of the landfill property is a low lying swampy area that also borders the Kayton Canal (see Figure 2) (Refs. 1; 5; 6, p. 10; 7; 8; 9; 10). The Savannah River is located approximately 1,500 feet north of the landfill (Ref. 1). The landfill is located within the 100 year flood plain for the Kayton Canal and Savannah River (Ref. 11).

The climate of Chatham County is classified as warm, humid, and subtropical (Ref. 12, pp. 64, 67). The mean annual precipitation for the area is 48 inches, and the mean annual lake evaporation is 44 inches, yielding a net annual precipitation of 4 inches (Ref. 13). The 2-year 24-hour rainfall for the area is 5 inches (Ref. 14).





SCALE 1 = 24,000

MODIFIED FROM USGS 7.5 MINUTE QUADRANGLE: SAVANNAH QUADRANGLE GEORGIA 1978




JORDAN SIGN COMPANY SAVANNAH, CHATHAM COUNTY, GEORGIA TDD No. 4T-01-10-A-007 EPA ID No. GAD003293057

FIGURE 1 - GENERAL SITE MAP



Tetra Tech EM Inc. START



JORDAN SIGN COMPANY PROPERTY WATER TREES TRAINAGE DITCH

JORDAN SIGN COMPANY SAVANNAH, CHATHAM COUNTY, GEORGIA EPA ID No. GAD003293057 TDD NO. 4T-01-10-A-007

FIGURE 2 - SITE LAYOUT MAP



TETRA TECH EM INC. START

2.2 SITE OPERATIONS AND REGULATORY HISTORY

The landfill, which is located on a 24.38-acre tract of land, was used for the disposal of construction debris and dredge spoils after the early 1960s until sometime prior to 1977. Hercules, Inc., reportedly had disposed of resin waste at the landfill at an unknown time. No other information is available concerning the types and quantities of waste deposited at the landfill (Refs. 2; 4; 5; 7; 8; 9; 10). The facility property is currently regulated under CERCLA (Refs. 15; 16).

2.3 PREVIOUS RELEASES AND INVESTIGATIONS

Several environmental investigations have been performed at the landfill. In May 1988, the EPA Field Investigation Team conducted a preliminary reassessment (PR) for the landfill (Ref. 4). General information regarding the landfill was collected during the investigation; however, no environmental samples were collected. The PR recommended a medium-priority screening site inspection (Ref. 4). On August 25, 1988, the Georgia Department of Natural Resources, Environmental Protection Division (EPD) conducted a field sampling investigation. The remains of deteriorated drums were visible in the northern section of the landfill property (Ref. 9, p. 2). The EPD collected two groundwater samples during the 1988 sampling investigation at the landfill. The groundwater samples were analyzed for selected inorganic constituents and volatile organic compounds (VOC) (Ref. 10, pp. 11, 12). No inorganic constituents or VOCs were detected in a background groundwater sample collected from a 360foot-deep well located at the Savannah Country Club, less than 0.25 mile south of the landfill property. An on-site groundwater sample was collected from a shallow boring on the northern portion of the landfill property, where several inorganics were detected at elevated concentrations (Ref. 10, p. 11). In June 1996, Black & Veatch Special Projects Corp. (B & V) conducted a site inspection prioritization (SIP) for the landfill. Due to the limited information available concerning waste types and quantities, as well as the limited sampling information, B & V recommended that additional sampling be conducted at the landfill (Ref. 5).

The landfill property is currently being proposed for commercial use by Competitive Power Ventures (CPV) of Newburyport, Massachusetts. In February and March 2001, Hussey, Gay, Bell and DeYoung Environmental, Inc. (HGBD), in conjunction with TRC Environmental Corporation, performed a limited Phase II environmental field investigation for the proposed CPV Terrapin Power Project site on the landfill property (Ref. 17, p. 1). Six soil borings were advanced and soil samples were collected to ascertain subsurface soil conditions. In addition, six surface soil and six sediment samples were collected from ditches along the northern and southern property boundaries and from areas of apparent fill, spoil piles, and solid waste disposal areas. A rotary drill rig with hollow-stemmed augers was used to advance the boreholes at the six soil sampling locations. Two soil samples were collected from each soil boring using split-spoon techniques. Soil samples were collected from the ground surface, and the

subsurface soil sample was collected from the soil-groundwater interface. Permanent monitoring wells were also installed in the surficial aquifer at each of the soil boring locations, and groundwater samples were collected (Ref. 17, pp. 5 - 8, Appendix II). All soil samples collected from the soil borings were analyzed for total priority pollutant metals, semivolatile organic compounds (SVOC), pesticides, ammonia, fluoride, and soil pH. Sediment samples collected from the ditch located along the northern property line were analyzed for the same parameters as the soil boring samples. Only a select number of the soil samples were analyzed for VOCs and for toxicity characteristic leaching procedure (TCLP) lead (Ref. 17, pp. 4, 5). Laboratory analytical results indicated the presence of arsenic at concentrations above the Georgia Hazardous Site Response Act (HSRA) Notification Concentration (NC) standard in three samples collected from the soil borings. Several other heavy metals were also detected in surface and subsurface soil samples but at concentrations below the HSRA NC standards. TCLP analysis of a soil sample collected from soil boring B-6 indicated a lead concentration of 9.6 milligrams per liter (mg/l). A TCLP lead concentration of 5 mg/L or more is characteristic of a hazardous waste under provisions of the Resource Conservation and Recovery Act (RCRA; 40 CFR, 261.24). (Ref. 17, p. 3; 18). After soil sampling, soil borings B-1 through B-4 were completed as permanent groundwater monitoring wells

MW-1 through MW-4, respectively. In addition, one existing on-site groundwater monitoring well (MW-5) was sampled. The available file material does not indicate when this well was installed or by whom (Ref. 17, p. 8). Analytical results from the initial groundwater sampling by HGBD personnel indicated the presence of arsenic, thallium, and antimony at concentrations above both federal and state drinking water maximum contaminant levels (MCL) (Ref. 17, p. 9).

2.4 POTENTIAL SOURCE AREAS

The 24.38-acre landfill is the only source evaluated.

3.0 ESI ACTIVITIES

This section outlines field observations made and sampling procedures followed at the site during the ESI. Individual subsections address the sampling investigation and rationales for specific ESI activities. The ESI was conducted in accordance with the EPA-approved site-specific sampling plan (SSSP) dated September 6, 2000.

3.1 SAMPLE COLLECTION METHODOLOGY AND PROCEDURES


Tetra Tech personnel collected 7 surface soil, 7 subsurface soil, 11 groundwater, 6 surface water, and 6 sediment samples during the week of March 26, 2001. ESI sampling locations are shown on Figure 3 and summarized in Tables 1 through 5. Tetra Tech personnel collected the surface soil samples from 0 to 6 inches below land surface (bls). Subsurface soil samples were collected from greater than 2 feet bls. In addition, surface water samples were collected from the water surface, and sediment samples were collected from the sediment-surface water interface along the on-site stormwater drainage ditch and from the Kayton Canal. Tetra Tech personnel followed sample collection procedures outlined in the SSSP developed in accordance with the EPA Science and Ecosystem Support Division (SESD) Region 4 "Environmental Investigations Standard Operating Procedures and Quality Assurance Manual" (EISOPQAM, May 1996).


3.2 ANALYTICAL SUPPORT AND METHODOLOGY

All samples collected during the ESI were analyzed through the EPA Contract Laboratory Program (CLP). The laboratories analyzed for EPA target compound list (TCL), VOCs, SVOCs, pesticides, and polychlorinated biphenyls (PCB). The samples were also analyzed for target analyte list inorganic substances (total metals and cyanide). EPA Region 4 SESD reviewed all data for compliance with the terms of the CLP. The complete set of analytical data sheets is presented in Appendix A.

3.3 ANALYTICAL DATA QUALITY AND DATA QUALIFIERS

All analytical data were subject to a quality assurance review as described in the EPA SESD laboratory data evaluation guidelines. In the text and analytical data tables presented in this report, some concentrations of the organic and inorganic parameters have been qualified with a "J," indicating that the qualitative analysis was acceptable; however, the quantitative value has been estimated. Other compounds may have been qualified with an "N," indicating that they were detected based on the presumptive evidence of their presence. This means that the compound was only tentatively identified, and its detection cannot be considered a positive indication of its presence. Results for some samples are reported with a "U" qualifier, meaning that an analysis was done; however, the constituent was not detected. Instead the reported number is the laboratory-derived sample quantitation limit (SQL) for the constituent in that sample. Sample results reported with an "R" qualifier indicate that the data are unusable. At times, miscellaneous organic compounds that do not appear on the TCL are reported with the data set. These constituents are qualified as "JN," indicating that they are tentatively identified at estimated quantities. An analysis for these constituents is not routinely conducted or reported, so





NOT TO SCALE

JORDAN SIGN COMPANY SAVANNAH, CHATHAM COUNTY, GEORGIA EPA ID No. GAD003293057 TDD NO. 4T-01-10-A-007

FIGURE 3 - SAMPLING LOCATION MAP



TETRA TECH EM INC. START

TABLE 1 SURFACE SOIL SAMPLING LOCATIONS AND RATIONALE

Sample Number	Location	Rationale
JS-01-SS	Approximately 100 feet north of the East President Street Extension, and 75 feet west of Dulany Road in a grassy area	Background surface soil sample for comparison to on-site sample results
	Coordinates: 32° 04' 20.1" N, 81° 04' 02.5" W	
JS-02-SS	Approximately 15 feet from permanent monitoring well MW-3.	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 19.8" N, 81° 03' 58.7" W	
JS-03-SS	Extreme northwest corner of landfill Coordinates: None recorded	Determine presence or absence of hazardous substances
JS-04-SS	Northwestern portion of landfill Coordinates: 32° 04' 29.8" N, 81° 03' 56.4" W	Determine presence or absence of hazardous substances
JS-05-SS	Eastern portion of spoil disposal area Coordinates: 32° 04' 19.2" N, 81° 03' 57.7" W	Determine presence or absence of hazardous substances
JS-06-SS	Approximately 100 yards west of the on- site apiary	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 23.5" N, 81° 03' 58.6" W	
JS-07-SS	Central portion of landfill	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 25.0" N, 81° 03' 54.7" W	

JS - Jordan Sign Company SS - Surface soil Notes:

TABLE 2 SUBSURFACE SOIL SAMPLING LOCATIONS AND RATIONALE

Sample Number	Location	Rationale
JS-01-SB	Approximately 100 feet north of the East President Street Extension, and 75 feet west of Dulany Road, in a grassy area	Background subsurface soil sample for comparison to onsite sample results
	Coordinates: 32° 04' 20.1" N, 81° 04' 02.5" W	
JS-02-SB	Approximately 15 feet from permanent monitoring well MW-3	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 19.8" N, 81° 03' 58.7" W	
JS-03-SB	Extreme northwest corner of landfill	Determine presence or absence of hazardous substances
	Coordinates: None recorded	
JS-04-SB	Northwest portion of landfill	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 29.8" N, 81° 03' 56.4" W	
JS-05-SB	Eastern portion of spoil disposal area	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 19.2" N, 81° 03' 57.7" W	
JS-06-SB	Approximately 100 yards west of the on-site apiary	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 23.5" N, 81° 03' 58.6" W	
JS-07-SB	Central portion of landfill	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 25.0" N, 81° 03' 54.7" W	or mular would buddington

Jordan Sign Company Subsurface soil Notes: JS - SB -

TABLE 3 GROUNDWATER SAMPLING LOCATIONS AND RATIONALE

Sample Number	Location	Rationale
JS-01-GW	Approximately 120 feet north of the East President Street Extension, and 75 feet west of Dulany Road in a wooded area	Background groundwater sample for comparison to on-site sample results
	Coordinates: 32° 04' 20.3" N, 81° 04' 2.2" W	
JS-02-MW	On-site permanent monitoring well MW-3 Coordinates: 32° 04' 19.9" N, 81° 03' 58.7" W	Determine presence or absence of hazardous substances
JS-05A-MW	On-site permanent monitoring well MW-5 Coordinates: 32° 04' 25.5" N, 81° 03' 56.1" W	Determine presence or absence of hazardous substances
JS-02A-MW	On-site permanent monitoring well MW-2 Coordinates: 32° 04' 21.3" N, 81° 03' 53.4" W	Determine presence or absence of hazardous substances
JS-01A-MW	On-site permanent monitoring well MW-1 Coordinates: 32° 04' 27.1" N, 81° 03' 53.0" W	Determine presence or absence of hazardous substances
JS-03-GW	Extreme northwest corner of landfill Coordinates: 32° 04' 30.1"N, 81° 03' 57.6" W	Determine presence or absence or hazardous substances
JS-05-GW	Eastern portion of spoil disposal area Coordinates: 32°04'19.2N, 81°03'57.7"W	Determine presence or abasence of hazardous substances
JS-01-PW	Savannah Country Club private well	Background groundwater sample for comparison to downgradient sample results
JS-08-DW	Savannah Water & Sewer Bureau well No. 8 (Edgewood Rd & Pierpont Ave)	Determine presence or absence of hazardous substances
JS-11-DW	Savannah Water & Sewer Bureau Well No. 11 (Pennsylvania Ave & Harrison St)	Determine presence or absence of hazardous substances

TABLE 3 (Continued)

GROUNDWATER SAMPLING LOCATIONS AND RATIONALE

Sample Number.	Location	Rationale
JS-16-DW	Eastern portion of spoil disposal area	Determine presence or absence of hazardous substances

Notes:

JS - Jordan Sign Company

DW - Savannah Water & Sewer Bureau Municipal Well

GW - Temporary monitoring well

MW - Permanent monitoring well

PW - Private well

TABLE 4 SURFACE WATER SAMPLING LOCATIONS AND RATIONALE

Sample Number	Location	Rationale
JS-01-SW	Storm water ditch, upgradient of the landfill	Background sample for comparison to on-site results
	Coordinates: 32° 04′ 17.7″ N, 81° 03′ 56.3″ W	
JS-02-SW	Storm water ditch, midway between Dulany Road and the background surface water sampling location	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 18.4" N, 81° 03' 58.7" W	
JS-03-SW	Storm water ditch, near intersection of Dulany Road and East President Street Extension	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 19.1" N, 81° 04' 01.2" W	
JS-04-SW	Confluence of storm water ditch and Kayton Canal	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 19.8" N, 81° 04' 04.2" W	
JS-05-SW	East bank of Kayton Canal, approximately 10 feet south of East President Street Extension bridge	Determine presence or absence of hazardous substances
	Coordinates: 32° 04' 18.8" N, 81° 04' 04.6" W	
JS-06-SW	Kayton Canal, at former outfall for the East President Street Water Treatment Plant	Control surface water sample for comparison to surface water samples from Kayton Canal
,	Coordinates: 32° 04' 23.1" N, 81° 04' 03.5" W	

Jordan Sign Company Surface water

TABLE 5
SEDIMENT SAMPLING LOCATIONS AND RATIONALE

Sample Number	Location	Rationale
JS-01-SD	Storm water ditch, upgradient of the landfill **	Background sediment sample for comparison to on-site results
JS-02-SD	Storm water ditch, midway between Dulany Road and the background surface water sampling location **	Determine presence or absence of hazardous substances
JS-03-SD	Storm water ditch, near intersection of Dulany Road and East President Street **	Determine presence or absence of hazardous substances
JS-04-SD	Confluence of storm water ditch and Kayton Canal **	Determine presence or absence of hazardous substances
JS-05-SD	East bank of Kayton Canal, approximately 10 feet south of East President Street bridge **	Determine presence or absence of hazardous substances
JS-06-SD	Kayton Canal, at former outfall for the East President Street Water Treatment Plant **	Control surface water sample for comparison to surface water samples from Kayton Canal

Notes: JS - Jordan Sign Company

SD - Sediment

** - Sediment sample coordinates are the same as the surface water sampling locations

background levels or SQLs are not generally available for comparison. The complete set of analytical data sheets is presented in Appendix A.

4.0 SOURCE SAMPLING

This section discusses the source areas evaluated at the facility and the sampling locations and analytical results of samples collected from the source areas. Source areas evaluated during this ESI include the entire landfill property.

ESI surface and subsurface soil sampling locations are shown on Figure 3 and described in Tables 1 and 2. ESI surface soil inorganic analytical results are summarized in Tables 6 and 7, respectively. ESI subsurface soil inorganic and organic analytical sampling results are summarized in Tables 8 and 9, respectively. Tables 1 and 2 are presented following Section 3.1; Tables 6 through 9 are presented following Section 4.2. Elevated concentrations of constituents are shaded in the tables. The concentration of a constituent is considered to be elevated if it is greater than or equal to three times the concentration detected in the background or control sample. In cases where a constituent was not detected in the background or control sample, any concentration equal to or greater than the SQL is considered to be elevated. The complete set of analytical data sheets is presented in Appendix A.

The following discussion of hazardous constituents detected at elevated levels in soil samples collected at the landfill includes those hazardous constituents that may pose a threat to human health or the environment.

4.1 SOURCE SAMPLING LOCATIONS AND ANALYTICAL RESULTS

Tetra Tech personnel collected six surface soil samples and six subsurface soil samples from various locations on the landfill property during the ESI. In addition, one background surface soil sample (JS-01-SS) and one background subsurface soil sample (JS-01-SB) were collected in a grassy area approximately 100 feet north of the East President Street Extension and 75 feet west of Dulany Road (Ref. 6, p. 21). The ESI on-site surface and suburface soil sampling locations are described in Tables 1 and 2 following Section 3.3.

Analytical results for surface soil samples collected at the landfill indicated elevated concentrations of several inorganic constituents of concern including aluminum, arsenic, barium, cadmium, cobalt, chromium, copper, lead, manganese, total mercury, nickel, silver, vanadium, and zinc (see Table 6). Aluminum was detected in three surface soil samples at elevated concentrations ranging from 7,600J milligrams per kilogram (mg/kg) in sample JS-04-SS to 14,000J mg/kg in sample JS-06-SS. Arsenic was detected at an elevated concentration of 51 mg/kg in surface soil sample JS-03-SS. Barium was detected

in two surface soil samples at elevated concentrations of 160 mg/kg in sample JS-04-SS and 240 mg/kg in sample

JS-03-SS. Cadmium was detected at an elevated concentration of 2.5 mg/kg in sample JS-04-SS. Chromium was detected in three surface soil samples at elevated concentrations ranging from 29 mg/kg in sample JS-06-SS to 320 mg/kg in sample JS-03-SS. Cobalt was detected at an elevated concentration of 23 mg/kg in sample JS-03-SS. Copper was detected in two surface soil samples at elevated concentrations of 160 mg/kg in sample JS-04-SS and 180 mg/kg in sample JS-03-SS. Lead was detected in two surface soil samples at elevated concentrations of 520 mg/kg in sample JS-04-SS and 2,500 mg/kg in sample JS-03-SS. Manganese was detected in three surface soil samples at elevated concentrations ranging from 360 mg/kg in sample JS-04-SS, to 1,300 mg/kg in sample JS-03-SS. Total mercury was detected in two surface soil samples at elevated concentrations of 0.81 mg/kg in sample JS-03-SS and 1.7 mg/kg in sample JS-04-SS. Nickel was detected in two surface soil samples at elevated concentrations of 58 mg/kg in sample JS-03-SS and 72 mg/kg in sample JS-04-SS. Silver was detected in two surface soil samples at elevated concentrations of 4.8J mg/kg in sample JS-04-SS and 7.0J mg/kg in sample JS-03-SS. Vanadium was detected in three surface soil samples at elevated concentrations ranging from 29 mg/kg in sample JS-04-SS to 46 mg/kg in sample JS-06-SS. Zinc was detected in two surface soil samples at elevated concentrations of 2,100 mg/kg in sample JS-04-SS and 2,400 mg/kg in sample JS-03-SS (see Appendix A).

Organic compounds detected at elevated concentrations in on-site surface soil samples were acetone, dieldrin, hepatchlor epoxide, 4,4'-DDE, 4,4'-DDD, 4,4'-DDT, gamma chlordane/2, PCB-1254, and PCB-1260 (see Table 7). Acetone was detected at an elevated concentration of 11,000 micrograms per kilogram (µg/kg) in surface soil sample JS-02-SS. Dieldrin was detected at elevated concentration of 30 µg/kg in sample JS-03-SS. Hepatchlor epoxide was detected at an elevated concentration of 17 µg/kg in surface soil sample JS-04-SS. 4,4'DDE was detected at an elevated concentration of 83 µg/kg in surface soil sample JS-04-SS. 4,4'-DDD was detected at elevated concentration of 49 µg/kg in surface soil sample JS-04-SS. 4,4'-DDT was detected at an elevated concentration of 280 µg/kg in surface soil sample JS-04-SS. Gamma chlordane/2 was detected at an elevated concentration of 85 µg/kg in sample JS-04-SS. PCB-1254 was detected at an elevated concentration of 880 µg/kg in sample JS-03-SS, and PCB-1260 was detected at elevated concentration of 310 µg/kg in surface soil sample JS-03-SS. Additionally, numerous miscellaneous organic compounds were detected in the surface soil samples (see Appendix A).

Analytical results for subsurface soil samples collected at the landfill indicated elevated concentrations of several inorganic constituents of concern, including aluminum, arsenic, barium, chromium, copper, lead, manganese, vanadium, and zinc (see Table 8). Aluminum was detected inf four subsurface soil samples at elevated concentrations ranging from 2,900J mg/kg in sample JS-07-SB to 15,000J mg/kg in sample

JS-03-SB. Arsenic was detected at an elevated concentration of 53 mg/kg in sample JS-04-SB. Barium was detected in four subsurface soil samples at elevated concentrations, ranging from 14 mg/kg in sample JS-07-SB to 57 mg/kg in sample JS-03-SB. Chromium was detected in four subsurface soil samples at elevated concentrations ranging from 3.1 mg/kg in sample JS-07-SB to 36 mg/kg in subsurface soil sample JS-03-SB. Copper was detected in four subsurface soil samples at elevated concentrations ranging from 5.6 mg/kg in sample JS-02-SB to 130 mg/kg in sample JS-04-SB. Lead was detected in three subsurface soil samples at elevated concentrations ranging from 21 mg/kg in sample JS-06-SB to 100 mg/kg in sample JS-04-SB. Manganese was detected in three subsurface soil samples at elevated concentrations ranging from 38 mg/kg in sample JS-06-SB to 70 mg/kg in sample JS-04-SB. Vanadium was detected at in three subsurface soil samples at elevated concentrations ranging from 19 mg/kg in sample JS-06-SB to 51 mg/kg in sample JS-03-SB. Zinc was detected in five subsurface soil samples at elevated concentrations ranging from 5.2 mg/kg in sample JS-02-SB to 470 mg/kg in sample JS-03-SB.

Organic compounds detected at elevated concentrations in on-site subsurface soil samples were acetone, benzo-a-pyrene, benzo(ghi)perylene, dieldrin, heptachlor epoxide, 4,4'-DDE, 4,4'-DDD, 4,4'-DDT, and gamma-chlordane/2 (see Table 9). Acetone was detected in two subsurface soil samples at elevated concentrations of 60J μ g/kg in sample JS-02-SB and 77 μ g/kg in sample JS-04-SB. Benzo(a)pyrene was detected in two subsurface soil samples at elevated concentrations of 530 μ g/kg in sample JS-04-SB and 560 μ g/kg in subsurface soil sample JS-07-SB. Benzo(ghi)perylene was detected in two subsurface soil samples at elevated concentrations of 860 μ g/kg in sample JS-04-SB and 1,500 μ g/kg in sample JS-07-SB. Dieldrin (40 μ g/kg), heptachlor epoxide (2.7J μ g/kg), 4,4'-DDE (7.3 μ g/kg), 4,4'-DDD (4.9J μ g/kg),

4,4'-DDT (20 μg/kg), gamma-chlordane/2 (10 μg/kg) were all detected at elevated concentrations in subsurface soil sample JS-04-SB. In addition, numerous miscellaneous organic compounds were detected at elevated concentrations in the subsurface soil samples (see Appendix A).

4.2 SOURCE CONCLUSIONS

The analytical results for on-site surface and subsurface soil samples indicate the presence of surficial and subsurface contamination at various locations throughout the landfill. Several inorganic constituents, including aluminum, arsenic, barium, cadmium, chromium, cobalt, copper, lead, manganese, mercury, nickel, silver, vanadium, and zinc, were detected at elevated concentrations in on-site surface soil samples. Inorganic constituents detected at elevated concentrations in on-site subsurface soil samples include aluminum, arsenic, barium, chromium, copper, lead, manganese, vanadium, and zinc. Organic compounds detected at elevated levels in on-site surface soil samples were acetone, dieldrin, heptachlor epoxide, 4,4'-DDE, 4,4'-DDD, 4,4'-DDT, gamma-chlordane/2, PCB-1254, and PCB-1260. Organic compounds detected at elevated concentrations in on-site subsurface soil samples were acetone, benzo(a)pyrene, benzo(ghi)perylene, dieldrin, heptachlor epoxide, 4,4'-DDE, 4,4'-DDD, 4,4'-DDT,

TABLE 6

SUMMARY OF INORGANIC ANALYTICAL RESULTS SURFACE SOIL SAMPLES

SAMPLE NUMBER									
	Background		On Site						
ANALYTE (mg/kg)	JS-01-SS	JS-02-SS	JS-03-SS	JS-04-SS	JS-05-SS	JS-06-SS	JS-07-SS		
Aluminum	1,800J	730J	9,500J	7,600J	430J	14,000J	3,000J		
Arsenic	2.8U		51	-	-		11		
Barium	18	6.7	240	160	4.2	34	12		
Cadmium	0.09U	20 Jan 19		2.5	-	77-1	-		
Calcium	1,000	880	21,000	26,000	550	1,600	2,500		
Chromium	6.4	2.4	320	41	07-18	29	3.2		
Cobalt	0.35U	- 1	. 23	-	-	-	4-		
Copper	9.1	5.6	180	160	- 3	24	8.6		
Iron	3,100	1,700	200,000	46,000	1,200	22,000	820		
Lead	50	8.6	2,500	520	1.9	26	9.0		
Magnesium	250	190	860	1,300	84	1,500	160		
Manganese	47	40	1,300	360	26	400	24		
Mercury (Total)	0.06U		0.81	1.7	-	-	-		
Nickel	2.0U	-	58	72		-	-		
Potassium	120J	70J	660J	720J	50J	1,100J	110J		
Silver	0.51U	-	7.0J	4.8J	-	_	-		
Sodium	100	100	340	490	100	310	140		
Vanadium	6.7U	-	31	29		46	2		
Zinc	36	25	2,400	2,100	12	75	83		

Notes:

mg/kg Milligrams per kilogram
JS Jordan Sign Company
SS Surface soil sample
U Constituent analyzed for but not detected; value reported is the sample quantitation limit
(SQL)

J Estimated value
-- Constituent analyzed for but not detected
Shaded areas indicate elevated concentrations of constituents

SUMMARY OF ORGANIC ANALYTICAL RESULTS
SURFACE SOIL SAMPLES

TABLE 7

		SAMPLE NUMBER								
	Background			On	Site					
COMPOUND (µg/kg)	JS-01-SS	IS-02-SS*		JS-04-SS	JS-05-SS	JS-06-SS	JS-07-SS			
Volatiles	-		-							
Acetone	110	11,000								
Methyl Acetate	2.J		3J		IJ		. 3J			
Extractables										
Benzaldehyde	380U			140J						
Phenanthrene	39J			79J						
Fluoranthene	160J		100J	170J		46J				
Pyrene	110J		98J	190J						
Benzo(a)anthracene	59J		56J	1101						
Chrysene	96J		84J	170J						
Benzo(b)fluoranthene	913		60J	170J						
Benzo(k)fluoranthene	713		57J	110J						
Benzo-a-pyrene	55J			120J						
Indeno(1,2,3-cd)pyrene	64J		- -	180J						
Dibenzo(a,h)Anthracene	380UJ			79J						
Benzo(ghi)perylene	380UJ -			1801		′				

TABLE 7 (CONTINUED)

SUMMARY OF ORGANIC ANALYTICAL RESULTS SURFACE SOIL SAMPLES

			SAM	PLE NUMBI	CR		
	Background			On	Site		
COMPOUND (ug/kg)	JS-01-SS	JS-02-SS	JS-03-SS	IS-04-SS	IS-05-SS	JS-06-SS	JS-07-SS
Pesticides/PCBs			-		•		_
Beta-BHC	1.9U						1.7 J
Heptachlor	1.9U		1.2J	2.8 JN			
Dieldrin	3.8U		30	320N			
Heptachlor Epoxide	1.9U			17			
4,4'-DDE	3.8U		39 N	83			
4,4'-DDD	3.7U			² > 49			
4,4'-DDT	3.8U			280			
Gamma-chlordane/2	1.9U		,	85			·
Methoxychlor	19Ú		22J				 .
Alpha-chlordane /2	1.9U		89N	110 N			
PCB-1254	38U		880				
PCB-1260	38U		310				

Notes:

Milligrams per kilogram
Jordan Sign Company
Surface soil sample
Constituent analyzed for but not detected; value reported is the sample quantitation limi. mg/kg JS SS

U

Estimated value

-- Constituent analyzed for but not detected
N Presumptive evidence of presence of material
Shaded areas indicate elevated concentrations of constituents

TABLE 8 SUMMARY OF INORGANIC ANALYTICAL RESULTS SUBSURFACE SOIL SAMPLES

	SAMPLE NUMBER On Site										
ANALYTE (mg/kg)	JS-01-SB	JS-02-SB	JS-03-SB	JS-04-SB	JS-05-SB	JS-06-SB	JS-07-SB				
Aluminum	280J	240J	15,000J	12,000J	320J	12,000J	2,900J				
Arsenic	1.6U	-	-	53	-	A	-				
Barium	2.7	2.2	57	52	3.3	25	14				
Calcium	520	580	9,800	5,500	820	1,600	510				
Chromium	1.2U		36	26		14	3.1				
Copper	-3.7U	5.6	58	130	-	12					
Iron	550	900	10,000	15,000	930	12,000	790				
Lead	1.2		74	100	-	21	3.2				
Magnesium	74	59	810	970	62	420	94				
Manganese	6.8	18	48	70	18	38	5.9				
Potassium	38UJ	200	720J	670J		320J	61J				
Sodium	120	94	790	390	96	200	130				
Vanadium	1.1U	- ,	51	39		19					
Zinc	4.3U	5.2	470	230	30	30	6.2				

mg/kg Milligrams per kilogram
JS Jordan Sign Company
SS Surface soil sample
U Constituent analyzed for but not detected; value reported is the sample quantitation limit
J Estimated value
-- Constituent analyzed for but not detected
Shaded areas indicate elevated concentrations of constituents

SUMMARY OF ORGANIC ANALYTICAL RESULTS
SUBSURFACE SOIL SAMPLES

TABLE 9

			SAM	PLE NUMB	ER		
	Background			On	Site		
COMPOUND (µg/kg)	IS-01-SR			JS-04-SB	JS-05-SB	IS-06-SB	JS-07-SB
Volatiles		•					
Acetone	110	60 J		77			
Methyl Acetate	110			. 3J			
Extractables							
Benzaldehyde	. 75J		120J	1,001			
Phenanthrene	350U						
Fluoranthene	350U						
Pyrene	350UJ						
Benzo(a)anthracene	350U			·			
Chrysene	350U						 .
Bis(2-cthylhexyl)phthalate	350U			680			'
benzo(b)fluoranthene	350U						
benzo(k)fluoranthene	350U		·		· ·		
benzo-a-pyrene	350U						
Indeno(1,2,3-cd)pyrene	350U						
Dibenzo(a,h)Anthracene	350UJ						
Benzo(ghi)perylene	· 350UJ					560J	

TABLE 9 (CONTINUED)

SUMMARY OF ORGANIC ANALYTICAL RESULTS SUBSURFACE SOIL SAMPLES

	SAMPLE NUMBER								
	Background			On	Site				
COMPOUND (µg/kg)	JS-01-SB	JS-02-SR	JS-03-SB	JS-04-SB	JS-05-SB	JS-06-SB	IS-07-SB		
Pesticides/PCBs									
Dieldrin	3.5U			40	 ·				
Heptachlor Epoxide	1.8U			2.7J 🌤	<u> </u>				
4,4'-DDE	3.5U			7.3		1.5JN			
4,4'-DDD	3.5U			4.9J					
4,4'-DDT	3.5U			20					
Gamma-chlordane/2	1.8U			10					
Endrin Ketone	3,5U			1.93					
Alpha-Chlordane /2	1.8U			14 N					

Notes:

Micrograms per kilogram
Jordan Sign Company
Surface soil sample
Constituent analyzed for but not detected; value reported is the sample quantitation limit. SS U

Estimated value

-- Constituent analyzed for but not detected.

N Presumptive evidence of presence of material
Shaded areas indicate elevated concentrations of constituents

5.0 PATHWAYS

This section discusses the groundwater migration, surface water migration, soil exposure, and air migration pathways. Additionally, this section discusses the targets associated with each pathway and draws pathway-specific conclusions. Sampling locations and analytical results for samples collected from the specific pathways are also discussed.

5.1 GROUNDWATER MIGRATION PATHWAY

Eleven groundwater samples were collected during the ESI. Sampling locations are depicted on Figure 3 and described in Table 3. Tetra Tech personnel installed and sampled three temporary monitoring wells; also sampled were four permanent monitoring wells, one supply well, and three drinking water wells maintained by the City of Savannah Water & Sewer Bureau (Ref. 6). Field parameters for groundwater samples are presented in Table 10. Inorganic analytical results for drinking water wells maintained by the City of Savannah are presented in Table 11. Temporary and monitoring well inorganic and organic analytical results are summarized in Tables 12 and 13, respectively. Tables 10, 11, 12, and 13 are presented following Section 5.1.2.

5.1.1 Geologic and Hydrogeologic Setting

Chatham County is located on the upper Georgia coast and extends to a maximum of 50 miles inland. The terrain is mostly level, and much of the area near the coast is marshy. The climate is influenced considerably by the coastal location and the subtropical latitude (Ref. 12, p. 67). The soil type at the landfill is classified as fresh tidal marsh. A fresh tidal marsh is adjacent to major fresh water streams. It occurs in the upper reaches of the marshland belt and is influenced by the daily tides. The soil material varies from place to place. The surface layer is a black or dark grayish-brown silty clay loam that contains many roots. Underneath the surface layer is a grayish-brown to black, soft, clayey material that has decaying logs, roots, and stumps intermixed. In some areas there are thin lenses of sand, and in other areas sandy material occurs at a depth of 3 to 8 feet (Ref. 12, p. 35).

The landfill is located in the coastal lowlands topographic division of the Coastal Plain physiographic province of Georgia. The terrain in the coastal lowlands consists of barrier islands, marshes, level plains and a series of terraces. Elevations in the coastal lowlands range from sea level to 100 feet above mean sea level (msl) (Refs. 1; 19).

The geologic units that underlie the landfill, listed in descending stratigraphic order, include

unconsolidated post-Miocene age deposits, the Hawthorn Group, the Suwannee Limestone, the Cooper Formation, the Ocala Limestone, the Gosport Sand equivalent, the Lisbon Formation, and the Tallahatta Formation. The unconsolidated post-Miocene deposits are composed of sand, gravel, clay, and marl and range from 50 to 100 feet thick in the landfill area. The Hawthorn Group is approximately 100 feet thick and consists of marl, clay, sand, and dolomite interbedded with phosphatic sandy clay and sandy dolomite. The Suwannee Limestone is approximately 80 feet thick and ranges from a fossiliferous limestone to a dense calcitized unfossiliferous limestone. The Cooper Formation consists of a phosphatic sandy marl. The Ocala Limestone consists of a fossiliferous, recrystallized, pourous limestone containing large solution cavities. The combined thickness of the Cooper Formation and Ocala Limestone is approximately 350 feet. The Gosport Sand equivalent consists of calcareous sand or sandy-limestone that is glauconitic at depth. The Lisbon Formation consists of glauconitic, sandy, clayey, and fossiliferous marl. The Tallahatta Formation is interbedded glauconitic sand and shale that grades to glauconitic argrillaceous and sandy fossiliferous limestone. The combined thickness of the Gosport Sand equivalent, the Lisbon Formation and the Tallahatta Formation ranges from 500 to 600 feet (Refs. 19, p. D24; 20).

Two major aquifers occur in the Savannah area: a surficial aquifer system and the Floridan Aquifer system. The surficial aquifer system is composed of the unconsolidated post-Miocene-age deposits. The underlying Floridan Aquifer system is primarily composed of carbonate units that range from Oligocene to middle Eocene age. In the Savannah area, the surficial aquifer is separated from the Floridan Aquifer system by the confining units of the Hawthorn Group (Refs. 19, pp. D18, D23; 21, p. 23).

Groundwater in the surficial aquifer is generally under unconfined conditions. The water level in this aquifer fluctuates seasonally, corresponding to seasonal variation in precipitation and evaporation. The surficial aquifer is recharged by infiltration of rainwater, generally in correlation with water from lakes, streams, and marshes (Ref. 19, p. D18).

The top of the Floridan Aquifer system occurs approximately 150 feet bls in the Savannah area. The Floridan Aquifer system can be divided into upper and lower permeable zones referred to as the Upper and Lower Floridan Aquifers are separated by a middle Eocene-age confining unit. The Floridan Aquifer system is confined below the low-permeability beds that occur in the middle of the Lisbon Formation. The Upper Floridan Aquifer consists of permeable beds of the Suwannee Limestone, Cooper Formation, and the Ocala Limestone. The Upper Floridan Aquifer is approximately 500 to 600 feet thick. In the Savannah area, the Upper Floridan Aquifer consists primarily of three permeable zones separated by locally confining units. The Lower Floridan Aquifer consists of permeable beds in the Gosport Sand equivalent and part of the Lisbon Formation. The Lower Floridan Aquifer is approximately 200 feet thick. In the site area, the Lower Floridan Aquifer responds to pumping from the Upper Floridan Aquifer. This response is indicated by the similarity, over

time, of water levels observed in the Upper and Lower Floridan Aquifers. This suggests that the Upper and Lower Floridan aquifers are hydrologically connected in the area (Refs. 20; 21).

5.1.2 Groundwater Sampling Locations and Analytical Results

Eleven groundwater samples were collected during the ESI (see Figure 3). Four groundwater samples were collected from on-site permanent monitoring wells, three samples were collected from temporary monitoring wells, three samples were collected from the Savannah Water & Sewer Bureau municipal wells, and one sample was collected from a supply well at the Savannah Country Club. The permanent monitoring wells are screened in the surficial aquifer, and the temporary wells installed during the ESI sampling activities were also screened in the surficial aquifer (Refs. 6; 17, Appendix II). Two background groundwater samples were collected due to the differences in depths of the municipal wells and the temporary and permanent monitoring wells on site. Background temporary monitoring well sample JS-01-GW was collected in a wooded area approximately 100 feet north of East President Street Extension, and 75 feet west of Dulany Road. The second background sample JS-01-PW, was collected from the Savannah Country Club private well upgradient of site influences; and the well is 480 feet deep and screened in the Floridan Aquifer. The Savannah Water & Sewer Bureau municipal wells are also screened in the Floridan Aquifer (Refs. 6; 22; 23). Groundwater samples JS-08-DW, JS-11-DW, and JS-16-DW were collected from City of Savannah Water & Sewer Bureua municipal wells located immediately east and southeast of the landfill. One of these wells (well 11) is located within 0.50 mile of the landfill (Refs. 1; 6; 22; 23; 24).

Arsenic, cadmium, lead, mercury, and zinc were detected at elevated levels in groundwater samples collected on site. Arsenic was detected at an elevated concentration of 730 micrograms per liter (µg/L) in groundwater sample JS-01A-MW. Cadmium was detected at an elevated concentration of 0.40J µg/L in groundwater sample JS-01A-MW. Lead was detected at elevated concentration of 49J µg/L in groundwater sample JS-05A-MW. Mercury was detected at a elevated concentration of 1.0J µg/L in groundwater sample JS-03-GW. Zinc was detected at elevated concentrations ranging from 93J µg/L in groundwater sample JS-05A-MW to 760J µg/L in sample JS-01A-MW. In addition, arsenic, lead, and zinc were detected in the municipal well samples; but, not at elevated concentrations (see Table 12).

Caprolactam and gamma-chordane/2 are the only organic constituents detected at elevated levels in on-site groundwater samples (see Table 13). Numerous miscellaneous organic componds were detected in the on-site groundwater samples. No organic compounds were detected at elevated concentrations in the municipal well samples (see Appendix A).

5.1.3 Groundwater Targets

Drinking water within a 4-mile radius of the landfill is obtained from municipal groundwater wells maintained by the Savannah Water & Sewer Bureau, the town of Thunderbolt Water System, and several small community systems (1; 22; 23; 24; 25). The City of Savannah and Thunderbolt municipal water supply is derived from wells that draw water from the Floridan Aquifer system. The City of Savannah Water & Sewer Bureau supplies water in a blended system from a total of 38 wells drilled approximately 450 feet into the Floridan Aquifer located throughout the greater Savannah area (Ref. 25). The Savannah Water & Sewer Bureau provides potable water to 68,425 connections, or approximately 189,161 people, through seven individual systems: Savannah Main (22 wells), Dutch Island (3 wells), Georgetown/Gateway (4 wells), Savannah Quarters (2 wells), Travis (3 wells), Whitemarsh Island (3 wells), and Wilmington Island (4 wells) (Refs. 1; 22; 23; 24; 25). Of the seven systems, wells for two of the systems are located within 4 miles of the site: Savannah Main (13 wells serving 92,222 persons) and Whitemarsh Island (1 well serving 1,163 persons). The water in these individual systems is blended prior to distribution, and is also distributed within each individual system. The nearest municipal well to the site (Savannah Main) is located within 0.50 mile southeast of the landfill (Refs. 1; 22; 23; 24; 25; 26).

The City of Thunderbolt maintains two municipal wells approximately 3.5 miles southeast of the site. Water from these wells is blended prior to distribution. These wells are located approximately 3.5 miles southeast of the site. Combined, these wells serve a total of 1,200 connections or approximately 3,108 persons (Refs. 1; 22; 23; 24; 25; 26).

No known private residences in the Savannah area obtain potable water from private wells that are completed in the surficial aquifer (Ref. 22). A total of approximately 96,493 people living within 4 miles of the landfill obtain potable water from public wells completed in the Floridan Aquifer system (Ref. 25). Table 14 provides a breakdown of the public drinking water well locations within 4 miles of the landfill and the number of people served by these wells.

TABLE 10

SUMMARY OF FIELD PARAMETERS GROUNDWATER SAMPLES

	Well		Final Field Parameters					
SampleLocation	Depth (ft)	рH	Conductivity	Temperature (°C)	Turbity (NTU)			
JS-01-GW	3	6.23	3.37	16.1	9			
JS-01A-MW	15.5	6.57	1.24	16.4	0			
JS-02A-MW	12.2	7.38	1.48 ·	15.4	. 0			
JS-02-MW	12	7.00	0.077	13.4	85			
JS-03-GW	3	NR	NR	NR	NR			
JS-05-GW	6	7.03	0.208	16.8	6			
JS-05A-MW	19	7.21	1.70	16.5	0			
JS-01-PW	480	8.65	0.227	17.2	0			
JS-08-DW	587	7.95	0.264	22.5	0			
JS-11-DW	714	8.0	. 0.254	22.0	0			
JS-16-DW	551 -	8.05	0.234	22.0	0			

Notes:

Feet
Degrees Celcius
Nephelometric Turbity Unit
Jordan Sign Company.
Not recorded
Municipal well
Temporary well
Monitoring well
Private well ft ℃ NTU JS NR DW GW MW PW

TABLE 11
SUMMARY OF INORGANIC ANALYTICAL RESULTS
POTABLE GROUNDWATER SAMPLES

ANALYTE (µg/L)	SAMPLE NUMBER							
Alvania (igh	Savannah Country Club Well	Savannah Water & Sewer Bureau Wells						
	JS-01-PW	JS-08-DW	JS-11-DW	JS-16-DW				
Arsenic	5.6U	2.4A	1.2	1.4				
Barium	13	14A	12	14				
Cadmium	0.40J							
Calcium	27,000	29A	24	· 24				
Iron	20U		0.57	0.17				
Lead	1.6UR		1.5					
Magnesium	8,300	8.7A	8.9	8.9				
Mercury	0.10J							
Potassium	1,400J	2.1A	2.0	1.8				
Strontium	NA	340A	370	380				
Sodium	9,500	12A	12	8.4				
Zinc	26 J	7.4 A	31	26				

Notes:		μg/L	Microgram per liter	Α	Average Value
		ĴŠ	Jordan Sign Company	NA	Not Analyzed
	٠.	DW	Municipal well groundwater sample	· R	Unusable Data
		PW	Private well groundwater sample		
		J	Estimated value		
		U	Constituent analyzed for but not detecte	d; value	reported is the sample quantitation limit
			Constituent analyzed for but not detecte	ed	• •

TABLE 12

SUMMARY OF INORGANIC ANALYTICAL RESULTS GROUNDWATER SAMPLES

			SAM	IPLE NUMBER			
	Background			On S	Site		
ANALYTE (µg/L)	JS-01-GW	JS-01A-MW	JS-02A-MW	JS-02-MW	JS-03-GW	JS-05-GW	JS-05A-MW
Aluminum	3,000J	4,900J		380J	3,200J	1,200J	2,400J
Arsenic	16U	730	••	*-			
Barium	160	50	120	12	50	9.1	170
Cadmium	0.40UJ	0.40J					
Calcium	92,000	150,000	240,000	17,000	510,000	37,000	280,000
Iron	57,000	23,000	7,000	2,100	13,000	2,000	17,000
Lead	4.3J		3.8J		5.0J		49J
Magnesium	62,000	14,000	15,000	1,400	34,000	1,800	24,000
Manganese	1,100	780J	930	56	960		810J
Mercury	0.10UJ				1.0J		
Potassium	18,000J	13,000J	9,300J	970J	36,000J	550J	15,000J
Sodium	430,000	96,000	65,000	2,400	120,000	3,200	110,000
Zinc	25J	760J	100J	30J	170J		93J

Notes:	mg/kg Milligrams per kilogram JS Jordan Sign Company	~9/1	?

GW Temporary well groundwater sample

MW Permanent monitoring well groundwater sample

U Constituent analyzed for but not detected; value reported is the sample quantitation limit.

J Estimated value

-- Constituent analyzed for but not detected

N Presumptive evidence of presence of material

N/A Not analyzed

Shaded areas indicate elevated concentrations of constituents

TABLE 13

SUMMARY OF ORGANIC ANALYTICAL RESULTS GROUNDWATER SAMPLES

	SAMPLE NUMBER									
	Background		On S		n Site					
ANALYTE (µg/L)	JS-01-GW	_JS-01A-MW	JS-02A-MW	JS-02-MW	IS-03-GW	JS-05-GW	JS-05A-MW			
Volatiles										
None					,					
Extractables										
Caprolactam	18	300	39	120			210			
Pesticides/PCBs										
Endosulfan I (Alpha)	0.050UJ		0.020JN							
4,4'-DDD	0.10U		0.052J	,	, 					
4,4'-DDE	0.10U		0.026JN							
Gamma-Chlordane/2	0.050U		0.59		·					

		m-crograms Milligrams per liter
Notes	μg/L	Milligrams per liter
	JS	Jordan Sign Company
	U	Constituent analyzed for but not detected; value reported is the sample quantitation limit
	J	Estimated value
		Constituent analyzed for but not detected
	N	Presumptive evidence of presence of material
		Shaded areas indicate elevated concentrations of constituents
	PCB	Polychlorinated biphenyl
	GW	Temporary well groundwater sample
•	MW	Permanent monitoring well groundwater sample
		· · · · · · · · · · · · · · · · · · ·

TABLE 14

FLORIDAN AQUIFER SYSTEM
DRINKING WATER WELLS AND POPULATION SERVED

Radial Total People Public Wellfield Number of People Served Distance Public Wells per Wellfield * Served 0 - 0.25 mile 0.25 - 0.5 mile Sav (Main) 7,094 7,094 1. 0.50 - 1 mile 2 7,094 Sav (Main) 14,188 1 - 2 miles Sav (Main) 2 7,094 14,188 4 7.094 2 - 3 miles Sav (Main) Thunderbolt 2 3,108 31,484 Sav (Main) 4 7,094 3 - 4 miles Sav (Whitemarsh) 1,163 29,539

Notes:

Sav = Savannah Water & Sewer Bureau

- * Savannah (Main): Serves 156,072 people via 22 wells; 156,072/22 wells = 7,094 people/well
- * Savannah (Whitemarsh): Serves 3,489 people via 3 wells; 3,489/3 wells = 1,163 people/well
- * Thunderbolt: Serves 1,200 connections via 2 wells; 1,200 x 2.59 (Chatham County persons per household) = 3,108 persons served

Total

96,493

5.1.4 Groundwater Conclusions

The groundwater migration pathway is of some concern at the landfill. Although groundwater samples collected from on-site temporary and permanent monitoring wells during the ESI indicated the presence of arsenic, cadmium, lead, mercury, zinc, and gamma-chlordane/2 at elevated concentrations, no known targets within a 4-mile radius of the landfill obtain potable drinking water from the surficial aquifer. Furthermore, in the Savannah area the surficial aquifer is separated from the Floridan Aquifer system by confining beds of the Hawthorn Group.

The groundwater migration pathway is of some concern due to the presence of numerous municipal wells within 4 miles of the landfill. However, no inorganic or organic constituents of concern were detected at elevated levels in the groundwater samples collected from the three City of Savannah Water & Sewer Bureau municipal wells completed in the Floridan Aquifer. In addition, approximately 96,493 persons obtain water from wells within a 4-mile radius of the landfill, with the nearest municipal well located within 0.50 mile of the landfill.

5.2 SURFACE WATER MIGRATION PATHWAY

Tetra Tech personnel collected six surface water and six sediment samples during the ESI. Surface water and sediment sampling locations are depicted on Figure 3 and described in Tables 4 and 5. Inorganic and organic analytical results for surface water samples are summarized in Tables 15 and 16, respectively. Inorganic and organic analytical results for sediment samples are summarized in Tables 17 and 18, respectively. Tables 15 through 18 are presented following Section 5.2.4.

5.2.1 Hydrologic Setting

Surface water runoff at the facility enters a storm water drainage ditch located between the East President Street Extension, and the southern edge fo the the facility property. This drainage ditch traverses the entire southern portion of the landfill property and drains into the Kayton Canal located approximately 100 feet west of the landfill (Ref. 6) (see Figure 2). The natural gradient for theKayton Canal is north to the Savannah River, located 0.25 mile north of the landfill (Refs. 1; 27). However, the Savannah Water & Sewer Bureau maintains a wastewater pump station on the northern end of the Kayton Canal, to regulate flow of the canal. The pump station prevents the flow from the canal from flowing into the Savannah River naturally. At times, there is no flow in the canal, and the canal characteristics are more like a pond or lake. If the water level in the canal is high, the water is pumped to the wastewater pump station, and then discharged to the Savannah River. In addition, there are tide gates at the wastewater pump station on the Savannah River; at times the tide gates do not function properly, resulting in salt water intrusion into the Kayton Canal (Ref. 27).

5.2.2 Surface Water and Sediment Sampling Locations and Analytical Results

Tetra Tech personnel collected six surface water and six sediment samples during the ESI. Background surface water and sediment samples JS-01-SW and JS-01-SD were collected from the storm water ditch upstream of the landfill. Control surface water and sediment sample JS-06-SW and JS-06-SD were collected from the Kayton Canal adjacent to the former Savannah Water & Sewer Bureau outfall on the Kayton Canal.

Inorganic constituents detected at elevated levels in surface water and sediment samples collected during the ESI include aluminum, barium, cadmium, and silver. Inorganic constituents of concern detected at elevated levels in sediment samples collected during the ESI include aluminum, arsenic, chromium, copper, lead, mercury, silver, vanadium, and zinc. Aluminum was detected at an elevated concentration of 1,800 µg/L in surface water sample JS-02-SW, and 14,000J mg/kg in sediment sample JS-05-SD. Arsenic was detected at an elevated concentration of 76 mg/kg in sediment sample JS-05-SD. Barium was detected at an elevated concentration of 60 µg/L in surface water sample JS-04-SW. Cadmium was detected at an elevated concentration of 0.40J µg/L in surface water sample JS-03-SW. Chromium was detected at an elevated concentration of 31 mg/kg in sediment sample JS-05-SD. Lead was detected in two sediment samples at elevated concentrations of 240 mg/kg in sample JS-02-SD and 280 mg/kg in sample JS-05-SD. Mercury was detected in three sediment samples at elevated concentrations of 0.18 mg/kg in sample

JS-04-SD and 0.97 mg/kg in sample JS-05-SD. Silver was detected at elevated concentration of 20 μg/L in surface water sample JS-02-SW. Silver was also detected in three sediment samples at elevated concentrations ranging from 32J mg/kg in sediment sample JS-04-SD to 130J mg/kg in sample JS-02-SD. Vanadium was detected at an elevated concentration of 46 mg/kg in sediment sample JS-05-SD.

Organic compounds detected at elevated concentrations in surface water samples collected during the ESI include chloroform and atrazine (see Table 16). Organic compounds detected at elevated concentrations in sediment samples collected during the ESI include include fluoranthene, phenanthrene, pyrene, benzo(a)anthracene, chrysene, bis(2-ethylhexyl phthalate, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3-cd)pyrene, dibenzo(a,h)anthracene, benzo(ghi)perylene, 4,4'-DDE, 4,4'-DDD, 4,4'-DDT, gamma-chlordane/2, and PCB-1260. Fluoranthene was detected at an elevated concentration of 7,400 mg/kg in sediment sample JS-05-SD. Phenanthrene was detected at an elevated concentration of 5,100 µg/kg in sample JS-05-SD. Pyrene was detected at an elevated concentration of 7,400J µg/kg in sample JS-05-SD. Benzo(a)anthracene was detected at an elevated concentration of 3,100 µg/kg in sample JS-05-SD. Chrysene was detected at an elevated concentration of 2,900 µg/kg in sample JS-05-SD. Bis(2-ethyhexyl)phthalate was detected at an elevated concentration of 1,300 µg/kg in sample JS-04-SD. Benzo(b)fluoranthene was detected at an elevated concentration of 2,300 µg/kg in sample JS-04-SD. Benzo(b)fluoranthene was detected at an elevated concentration of 2,300 µg/kg in sample JS-04-SD. Benzo(b)fluoranthene was detected at an elevated concentration of 2,300 µg/kg in sample JS-04-SD. Benzo(b)fluoranthene was detected at an elevated concentration of 2,300 µg/kg in sample JS-04-SD.

SD. Bis(2-ethyhexyl)phthalate was detected at an elevated concentration of 1,300 µg/kg in sample JS-04-SD. Benzo(b)fluoranthene was detected at an elevated concentration of 2,300 µg/kg in sample JS-05-SD. Benzo(k)fluoranthene was detected at an elevated concentration of 2,200 µg/kg in sample JS-05-SD. Benzo-a-pyrene was detected at an elevated concentration of 2,400 µg/kg in sample JS-05-SD. Indeno(1,2,3-cd)pyrene was detected at an elevated concentration of 1,900 µg/kg in sample JS-05-SD. Dibenzo(a,h)anthracene was detected at an elevated concentration of 790 J µg.kg in sample JS-05-SD. Benzo(ghi)perylene was detected in two sediment samples at elevated concentrations of 250J µg/kg in sediment sample JS-04-SD to 820J µg/kg in sample JS-05-SD. 4,4'-DDE was detected at an elevated concentration of 67 µg/kg in sample JS-05-SD.

4,4'-DDD was detected at an elevated concentration of 13 μ g/kg in sample JS-05-SD. 4,4'-DDT was detected at an elevated concentration of 84 μ g/kg in sample JS-05-SD. Gamma-chlordane/2 was detected at an elevated concentration of 22 μ g/kg in sample JS-05-SD. PCB-1260 was detected at an elevated concentration of 63 μ g/kg in sample JS-05-SD.

5.2.3 Surface Water Targets

The Jordan Sign Company property is situated on approximately 20 acres of land classified as Palustrine scrub-shrub wetlands. In addition, approximately 0.25 mile of Palustrine scrub-shrub wetlands are located along the east bank of the Kayton Canal (Ref. 28). No surface water intakes are located on the Kayton Canal. The Kayton Canal is used for recreational fishing (Refs. 29; 30).

5.2.4 Surface Water Conclusions

The surface water migration pathway is a major concern at the Jordan Sign Company site. Elevated levels of inorganic constituents of concern detected in surface water samples collected during the ESI include aluminum, barium, cadmium, and silver. Elevated levels of inorganic constituents of concern detected in sediment samples collected during the ESI include aluminum, arsenic, chromium, copper, lead, mercury, silver, vanadium, and zinc. Organic compounds detected at elevated concentrations in surface water samples collected during the ESI include atrazine and chloroform. Organic compounds detected at elevated concentrations in sediment samples collected during the ESI include fluoranthene, phenanthrene, pyrene, benzo(a)anthracene, chrysene,bis(2-ethylhexyl phthalate, benzo(b)fluoranthene, benzo(ghi)perylene, benzo(k)fluoranthene, benzo(a)pyrene,indeno(1,2,3-cd)pyrene, dibenzo(a,h)anthracene, benzo(ghi)perylene, 4,4'-DDE, 4,4'-DDD, 4,4'-DDT, gamma-chlordane/2, and PCB-1260; the presence of these chemicals constitute an observed release of hazardous substances to the Kayton Canal which is utilized for recreational purposes, including fishing. An observed release of hazardous substances was also documented to the on-site palustrine scrub-shrub wetlands and the palustrine scrub-shrub wetlands located along the Kayton Canal.

TABLE 15 SUMMARY OF INORGANIC ANALYTICAL RESULTS SURFACE WATER SAMPLES

	SAMPLE NUMBER								
ANALYTE	Background	Stormwater	Ditch	Control	Kayton Canal				
(µg/L)	JS-01-SW	JS-02-SW	JS-03-SW	JS-06-SW	JS-04-SW	JS-05-SW			
Aluminum	290J	1,800J		830J	780J	730J			
Barium	100	170	130	21	60	26			
Cadmium	0.40UJ		0.40J	0.40J					
Calcium	68,000	110,000	160,000	51,000	88,000	55,000			
Iron	1,600	4,500	870	1,200	1,500	970			
Lead	1.6UR	53J		8.3J	11J	5.8J			
Magnesium	4,000	8,200	12,000	38,000	26,000	37,000			
Manganese	92	170Ј	230	150	170	170J			
Potassium	4,600J	4,600J	5,400J	18,000J	12,000J	18,000J			
Silver	1.0U	20		0.74U					
Sodium	15,000	17,000	24,000	250,000	150,000	240,000			
Zinc	56J	160J		723	58J	64J			

Notes:

Micrograms per liter
Jordan Sign Company
Surface water
Constituent analyzed for but not detected; value reported is the sample quantitation limit
Estimated value
Data Unusable

μg/L JS SW U J R

TABLE 16

SUMMARY OF ORGANIC ANALYTICAL RESULTS SURFACE WATER SAMPLES

	SAMPLE NUMBER									
	Background Stormwater Ditch			Control	e e Seguir	n Canal				
ANALYTE (µg/L)	JS-01-SW	JS-02-SW	JS-03-SW	JS-06-SW	JS-04-SW	JS-05-SW				
Volatiles										
Chloroform	1.0U	••		1.0U		1.2				
Extractables										
Atrazine	5 J	5 J	5 J	5 J	110J					
Pesticides/PCBs										
None			_	•						

•		
Notes:	μg/L	Micrograms per liter
	JS	Jordan Sign Company
	SW-	Surface water sample
	U	Constituent analyzed for but not detected; value reported is the sample quantitation limit (SQL)
•	J	Estimated value
		Constituent analyzed for but not detected.
		Shaded areas indicate elevated concentrations of constituents
	PCB	Polychlorinated biphenyl

TABLE 17 SUMMARY OF INORGANIC ANALYTICAL RESULTS SEDIMENT SAMPLES

\$1.437.00 m.s	SAMPLE NUMBER										
ANALYTE (mg/kg)	Background	Background Stormwater Ditch		Control		Kayton Canal					
	JS-01-SD	JS-02-SD	JS-03-SD	· JS-06-SD	JS-04-SD	JS-05-SD					
Aluminum	4,900J	8,100J	5,200J .	2.800J	2,900J	14.000J					
Arsenic	8.4U			7.0U		76					
Barium	60	110	56	26	36	95					
Calcium	12,000	8,900	. 4,600	7,000	1,700	2,200					
Chromium	.16	36	15	7.9	10	31					
Copper	31	80	22	21	25	120					
Iron ·	8,100	15,000	7,200	5,100	4,700	16,000					
Lead	46	240	61	51	62	280					
Magnesium	1,100	1,200	970	1,300	610	1,700					
Manganese	120	130	77	62	31	80					
Total Mercury	0.09U	0.26		0.10U	0.18	0.97					
Potassium	460J	290J	370J	290J	200J	720J					
Silver	7.7U J	்த் 130J	22J	1.3UJ	32J						
Sodium	280	340	210	360	360	790					
Vanadium	27 .	35	21	8.7U		46					
Zinc	200	270	120	100	110	160					
Cyanide	· 0.28U			0.23U	2.0						

mg/kg JS SD U J Milligrams per kilogram Jordan Sign Company Notes:

Sediment
Constituent analyzed for but not detected; value reported is the sample quantitation limit

Estimated value

TABLE 18 SUMMARY OF ORGANIC ANALYTICAL RESULTS SEDIMENT SAMPLES

	Background	The second of the second of	ater Ditch	Control	Kayton	Canal
ANALYTE (μο/kg)	JS-01-SD	JS-02-SD	JS-03-SD	JS-06-SD	JS-04-SD	JS-05-SD
Volatiles						
Methyl Acetate	2Ј		4J	6J		
Methyl Ethyl Ketone	15U		22J	13U ·		
Extractables .						
Phenol	510U		140J	440U		
(3-and/or4-)Methylphenol	510U		350J	440U		
Napththalene	510U			440U		91J
2-Methylnaphthalene	510U			440U		110J
Acenaphthylene	510U		·	440U		320J
Acenaphthene	510U		·	440U		200J
Dibenzofuran	510U	'		440U		190Ј
Fluorene	510U			440U		250J
Fluoranthene	100J	240J	160J	180J	260J	7,400
Phenanthrene	510U	92J		63J	100J	5,100
Anthracene	510U	/		440U		1,200
Carbazole	510U			440U		280J
Pyrene	100J	250J	160 J	160J	260J	7,400J
Benzo(a)anthracene	510U	110J	86J	76J	110J	3,100
Chrysene	90J	170J .	120J ,	130J	160J	2,900
Bis(2-ethylhexyl)phthalate	· 510U	••		520U	1,300	
Di-n-octylphthalate	510U			440U	1,400	1
Benzo(b)fluoranthene	80J	170J	140J	150J	130J	2,300
Beno(k)fluoranthene	62J	110J	110J	91J	150J	2,200
Benzo-a-Pyrene	58J	120J	100Ј	110J	130J	2,400
Indeno(1,2,3-cd)pyrene	72 J	130J	110J	120J	140J	1,900
Dibenzo(a,h)anthracene	⁵ 510UJ			50J	·	790J
Benzo(ghi)perylene	52J	88J .	75J	63J	250J	820J
Pesticides/PCBs						
Endosulfan I (Alpha)	2.6 UR			2.3UR		0.67J

TABLE 18 (CONTINUED) SUMMARY OF ORGANIC ANALYTICAL RESULTS SEDIMENT SAMPLES

	SAMPLE NUMBER									
	Background Stormwater Ditch			Control	Kayton Canal					
ANALYTE (µg/kg)	JS-01-SD	JS-02-SD	JS-03-SD	JS-06-SD	JS-04-SD	IS-05-SD				
Dieldrin	5.1U			4.4U		19N				
4,4'-DDE	1.4J	3.4JN	4.3J	3.4J	. 4.7JN	67				
4,4'-DDD	5.1U	2.2J	5,6 JN	. 2.1J	5.0J	13				
4,4'-DDT	5.1U			4.4U		84				
Alpha-Chlordane/2	2.6U	2.2JN	2.8J	4.2N	8.0N					
Gamma-Chlordane/2	2.6U	1.7J	1.8 J	2.3U	6.5N	22				
PCB-1254	51U			44						
PCB-1260	51U			44U		63				

Notes:	μg/kg	Micrograms per kilogram
	JS	Jordan Sign Company
	SD	Sediment sample
•	. U	Constituent analyzed for but not detected; value reported is the sample quantitation limit.
	1	Estimated value
		Constituent analyzed for but not detected.
	N	Presumptive evidence of presence of material
		Shaded areas indicate elevated concentrations of constituents
	PCB	Polychlorinated biphenyl
	. R	Data Unusable

5.3 SOIL EXPOSURE PATHWAY AND AIR MIGRATION PATHWAY

During the ESI, Tetra Tech personnel collected six surface soil, and six subsurface soil samples from the landfill property. ESI surface soil and subsurface soil sampling locations are described in Tables 1 and 2 and are shown on Figure 3. Surface soil inorganic and organic analytical results are summarized in Tables 6 and 7, respectively. Subsurface soil inorganic and organic samples are summarized in Tables 8 and 9, respectively. Tables 6, 7, 8, and 9 are presented following Section 4.1:

5.3.1 Physical Conditions

The land use surrounding the landfill is commercial and industrial (Ref. 1). The Southern States Phosphate and Fertilizer facility is located to the east-northeast portion of the landfill. Ind Chem, Inc. is located adjacent to the southeast corner of the landfill. The Savannah Country Club and golf course is located immediately southeast of the landfill across the East President Street Extension. Dulany Road borders the landfill property on both the west and north. Located west of Dulany Road is a wooded area situated on the east bank of the Kayton Canal. The area directly south of the landfill property is a low lying swampy area that also borders the Kayton Canal (Refs. 1; 5; 6; 27). Although the facility is partially fenced, the property is accessible to the public (Ref. 6).

5.3.2 Soil and Air Sample Locations and Analytical Results

On-site surface and subsurface soil sampling locations and analytical results are described in Tables 1 and 2, and discussed in Section 4.1.

5.3.3 Soil and Air Targets

The soil exposure pathway is of some concern at the landfill. Access to the landfill property is partially restricted by fences. There are no on-site workers (Ref. 6). The nearest residential areas are located approximately 0.5 mile southeast of the landfill (Ref. 1). Two schools are located approximately 1 mile south of the landfill property (Ref. 1). The population within 1 radial mile of the landfill is 4,529 people (Ref. 31).

The landfill is located in a moderately populated area; the number of people residing within a 4-mile radius of the landfill is distributed as follows: 0 to 0.25 mile, 0 persons; 0.25 to 0.5 mile, 140 persons; 0.5 to 1 mile, 4,389 persons; 1 to 2 miles, 27,115 persons; 2 to 3 miles, 26,461 persons; and 3 to 4 miles, 30,513 persons (Ref. 31). Several federally designated endangered and threatened species inhabit this part of Georgia; however, specific habitat locations are not known (Ref. 32).

5.3.4 Soil and Air Conclusions

The soil exposure pathway is of some concern at the landfill. The inactive landfill is situated in a mixed industrial and commercial area of Savannah. Inorganic and organic constituents have been detected at elevated levels in samples collected from the landfill property. However, no air samples have been collected. The air migration pathway is of minimal concern due to the limited targets within a 4-mile radius of the facility.

6.0 SUMMARY AND CONCLUSIONS

The Jordan Sign Company property consists of an inactive landfill encompassing approximately 24.38 acres. Source areas evaluated at the site include the former landfill. Analytical results for on-site surface and subsurface soil samples indicated the presence of inorganic and organic contaminants including aluminum, arsenic, barium, cadmium, cobalt, chromium, copper, lead, manganese, mercury, nickel, silver, vanadium, zinc, acetone, dieldrin, heptachlor epoxide, 4,4'-DDE, 4,4'-DDD, 4,4'-DDT, gamma-chlordane/2, PCB-1254, and PCB-1260.

The groundwater migration pathway is a significant concern at the Jordan Sign Company site. Although arsenic, lead, mercury, and zinc are inorganic constituents of concern detected at elevated levels in groundwater samples collected from on-site temporary and permanent monitoring wells, and gamma-chlordane/2 was detected at an elevated level in an on-site groundwater sample, no known targets located within a 4-mile readius of the landfill obtain potable drinking water from the surficial aquifer. Furthermore, in the Savannah area the surficial aquifer is separated from the Floridan Aquifer system by confining beds of the Hawthorn Group.

The groundwater migration pathway is of some concern due to the presence of numerous municipal wells within 4 miles of the landfill. However, no inorganic or organic constituents of concern were detected at elevated levels in the groundwater samples collected from the three City of Savannah Water & Sewer Bureau municipal wells completed in the Floridan Aquifer. In addition, approximately 96,493 people obtain water from wells within a 4-mile radius of the landfill; with the nearest well located within 0.50 mile of the landfill.

The surface water migration pathway is also a major concern at the Jordan Sign Company site. Inorganic contaminants detected at elevated concentrations in surface water and sediment samples collected at the landfill and downstream of the landfill include aluminum, arsenic, barium, cadmium, chromium, copper, lead, mercury, silver, vanadium, and zinc. Organic contaminants detected at elevated concentrations in sediment samples collected at the landfill and downstream of the landfill include fluoranthene, phenanthrene, pyrene, benzo(a)anthracene, chrysene, bis(2-ethyhexyl phthalate, benzo(b)fluoranthene,

benzo(k)fluoranthene, benzo(a)pyrene, indeno(1,2,3-cd)pyrene, dibenzo(a,h)anthracene, benzo(ghi)perylene, 4,4'-DDE, 4,4'-DDD, 4,4'-DDT, gamma-chlordane/2, and PCB-1260, constituting an observed release of hazardous substances to the Kayton Canal which is utilized for recreational purposes, including fishing. An observed release of hazardous substances was also documented on the on-site palustrine scrub-shrub wetlands and the palustrine scrub-shrub wetlands located along the Kayton Canal.

The soil exposure pathway is of some concern. Both inorganic and organic constituents have been detected at elevated levels in soil samples collected on the landfill property. The area surrounding the Jordan Sign Company site is commercial and industrial. The Southern States Phosphate and Fertilizer facility is located adjacent to the east-northeast portion of the landfill. Ind Chem, Inc., is located adjacent to the southeast corner of the landfill. The Savannah Country Club and golf course is located immediately southeast of the landfill across the East President Street Extension. Dulany Road borders the landfill property on both the west and north. Located west of Dulany Road is a wooded area, situated on the east bank of the Kayton Canal. The nearest residential area is 0.50 mile southeast of the landfill. Two schools are located approximately 1 mile south of the landfill. The landfill property is partially fenced; therefore, the property is potentially accessible to local residents. The population within a 4-mile radius of the landfill is 88,618 people. The population within 1 radial mile of the landfill is 4,529 people. In addition, several federally designated endangered and threatened species inhabit this part of Georgia; however, specific habitat locations are not known.

Based on the analytical results of samples collected during the ESI, further action is recommended for the Jordan Sign Company site, including further characterization of the Kayton Canal.

REFERENCES

- 1. U.S. Geological Survey (USGS). 7.5-minute Series Topographic Quadrangle Maps of Georgia: Fort Pulaski 1978; Garden City 1980; Limehouse 1980; Savannah 1978, scale 1:24,000.
- 2. U.S. Environmental Protection Agency (USEPA), Potential Hazardous Waste Site, Identification and Preliminary Assessment, EPA Form 2070-2, Prepared by Jennifer Kaduck, December 11, 1979.
- 3. USEPA, Potential Hazardous Waste Site, Site Inspection Report, EPA Form 2070-13, prepared by Gilda Knowles, Georgia Department of Natural Resources, Environmental Protection Division, September 28, 1988.
- 4. NUS Corporation . "Preliminary Reassessment for Jordan Sign Company, Savannah, Georgia." May 3, 1988.
- 5. Black & Veatch Special Projects Corp. "Site Inspection Prioritization for Jordan Sign Company, Savannah, Chatham County, Georgia". May 3, 1996.
- 6. Tetra Tech EM Inc., Field Logbook No. 68-W-00-1200015 for the Expanded Site Inspection conducted at the Jordan Sign Company conducted during the week of March 26, 2001.
- 7. Chatham County, Georgia, Property Deed. Record Book 104-C, Folio 187. August 2, 1974.
- 8. Tetra Tech EM Inc. "Property Access Information for Jordan Sign Company." February 11, 2000.
- 9. Georgia Department of Natural Resources. "Trip Report for the Jordan Sign Company." December 12, 1988.
- 10. Georgia Department of Natural Resources. "Screening Site Investigation Report for the Jordan Sign Company." December 30, 1988.
- 11. Federal Emergency Management Agency. "Flood Insurance Rate Map for Chatham County, eorgia." Panel 85 of 220. May 19, 1987.
- 12. U.S. Department of Agriculture, Soil Conservation Service. <u>Soil Survey of Bryan and Chatham</u> Counties, Georgia, 1974.
- 13. U.S. Department of Commerce, National Oceanic and Atmospheric Administration, Climatic Atlas of the United States, Washington, DC: Government Printing Office (GPO), June 1968, Reprint: 1983.
- 14. U.S. Department of Agriculture, Rainfall Frequency Atlas of the United States, Technical Paper No. 40, 1961.
- USEPA. CERCLIS Hazardous Waste Sites. Results are Based on Data Extracted on May 10, 2001. On-line Address: http://www.epa.gov/superfund/sites/cursites/c3ga/s0401342.htm.
- 16. USEPA. RCRA Info Query Results. Results are Based on Data Extracted on August 10, 2001. On-line Address: http://oaspub.epa.gov/enviro/fii_retreive.
- 17. Hussey Gay Bell & De Young Environmental Inc.. "Limited Phase II Environmental Field Investigation, CPV Terrapin Power Project, Savannah, Georgia." April, 2001.
- 18. National Archives and Records Administration, Office of the Federal Register, Code of Federal Regulations. "Protection of Environment, Chapter 40, Parts 260 to 299". July 1, 1996.
- 19. Krause, Richard E. and Randolph, Robert B. "Hydrology of the Floridan Aquifer System in Southeast Georgia and Adjacent Parts of Florida and South Carolina." U.S. Geological Survey Professional Paper 1403-D. Washington, DC. 1989.
- 20. Miller, James A., . "Hydrogeologic Framework of the Floridan Aquifer System in Florida and in Parts of Georgia, Alabama, and South Carolina." U.S. Geological Survey Professional Paper 1403- B. Washington, DC 1986.

- 21. Counts, Harlan B. and Ellis Donsky. "Salt-Water Encroachment Geology and Ground-Water Resources of Savannah Area Georgia and South Carolina." U.S. Geological Survey Water-Supply Paper 1611. Washington, DC 1963.
- 22. Tetra Tech EM Inc. Record of telephone conversation between David L. Brown, Environmental Scientist, and A.J. Oumgwitz, Georgia Department of Natural Resources, Environmental Protection Division (GDNR EPD). Subject: Surficial Aquifer Usage in Savannah, Georgia. July 16., 2001.
- 23. Tetra Tech EM Inc. Record of telephone conversation between David L. Brown, Environmental Scientist, and Mike Coon, Savannah Water Department. Subject: Water Systems Within the City of Savannah Water Operations. July 20, 2001.
- 24. Tetra Tech EM Inc., Field Logbook for the Expanded Site Inspection at Latex Construction In Thunderbolt, Chatham County, Georgia, week of March 27, 2001.
- 25. Tetra Tech EM Inc. Record of telephone conversation between Sandra Harrigan, Biologist, and Kenny Dumas, Savannah Water Department. Subject: Well locations for the City of Savannah Water Department. March 23, 2001.
- 26. U.S. Department of Commerce, Bureau of the Census, 1990 CPH-1-26, 1990 Census of Population and Housing, Summary Population and Housing Characteristics, Georgia, August 1991.
- 27. Tetra Tech EM Inc. Record of telephone conversation between David L. Brown, Environmental Scientist, and Pete Shonka, City of Savannah Storm Water Management. Subject: Kayton Canal. June 25, 2001.
- 28. U.S. Fish and Wildlife Service (USFWS), national Wetlands Inventory Map of Savannah, Georgia, 1997, Scale 1: 40,000.
- 29. Tetra Tech EM Inc. Record of telephone conversation between David L. Brown, Environmental Scientist, and Tim Barrett, Biologist, GDNR EPD, Fisheries Divsion, Region 7. Subject: Fishing in Kayton Canal. June 25, 2001.
- 30. Tetra Tech EM Inc. Record of telephone conversation between David L. Brown, Environmental Scientist, and Shannon Wisness, Environmental Specialist III, GDNR EPD. Subject: Fishing in Kayton Canal. June 25, 2001.
- 31. M.F.Wendt, Information Specialist, Tetra Tech EM Inc., Project Note to File for Jordan Sign Company, Savannah, GA, July 12, 2001. Subject: Population within distance rings for Jordan Sign Company, Savannah, GA.
- 32. USFWS, Endangered and Threatened Species of the Southeastern United States, 1992.

In 1996, EPA's Science and Ecosystems Support Division (SESD) conducted a case development investigation, during which, soil, sediment, surface water, and groundwater samples were collected from the Southern States Phosphate & Fertilizer Company, and groundwater and a soil sample were collected from the "landfill", also known as the Jordan Sign Site. The subsurface soil sample collected from the landfill contained a variety of heavy metals contamination, including arsenic at a concentration of 15 mg/kg, exceeding the Region III risk based concentration (RBC) value for arsenic (3.8 mg/kg) by almost 400 percent.

With the proposed top layers of sand by CPV, the risk of exposure to contaminants in soil in the landfill are taken away; however, the transfer to groundwater is an unknown. We have not thoroughly characterized the contents of the landfill; therefore, it is not known what the highest concentrations of waste contaminants in the landfill are. Data from previous investigations of soils from the landfill are sparse. Here is a table of some of the data EPA found. There could be more data that we didn't include here:

Date Type of Investigation Contaminant / Concentration Soil Sample Depth

arsenic/15 mg/ks so subsurface (don't know depth)
ans 33 ms/kg - LF downgrad 11/96 EPA CDIE 11/96 E14 CD18 copper 1400 5/2 gw. strontium 850 5516 " zine 110 5/L AL 16 mg Mn 35 mg/c Hg 2000sh certar Co 10 11 11

Co 16 downgrad. LP

Cr 41 mg/kg center LF

Cr 74 - 1 Cr 74 - downgrad Ef Ni 68 Lf-downgred read 180 center LF, 72 downers

CASE DEVELOPMENT INVESTIGATION EVALUATION SOUTHERN STATES PHOSPHATE & FERTILIZER CO. SAVANNAH, GEORGIA SESD PROJECT NO. 97-0033 NOVEMBER 1996

INTRODUCTION

During the week of November 4, 1996 the U.S. Environmental Protection Agency (US-EPA) Region 4, Science and Ecosystem Support Division (SESD), conducted a case development investigation and evaluation (DIE) at the Southern States Phosphate & Fertilizer Co. (S.P.) in Savannah, Georgia. The investigation was requested by the RCRA Enforcement and Compliance Branch (RCRA-ECB) and the Georgia Environmental Protection Division (GA-EPD) to evaluate potential releases from waste storage areas, a landfill, and an acid storage area. The study participants included:

Fred Sloan	US-EPA	(SESD)
Art Masters	US-EPA	(SESD)
Milton Henderson	US-EPA	(SESD)
Shayla Beam	US-EPA	(SESD)
Jack Dempsey	GA-EPD	(Atlanta)
Greg Thomas	GA-EPD	(Atlanta)

This investigation had multiple objectives. A waste pile was investigated to determine if the material was a hazardous waste, a former waste pile area was investigated to determine if a release had occurred, and a micronutrient pile was investigated to determine if it had originated from a hazardous waste (concentrated media samples). In addition, ponds and ditches were investigated to determine if a release had occurred (surface water and sediment samples). Finally groundwater and soil were was investigated to determine if a release had occurred in the area of one of the ponds, the sulfuric acid storage area, or the former landfill (soil and groundwater samples).

BACKGROUND

Fertilizer manufacturing has been done on the Southern States Phosphate & Fertilizer Co. site since 1903. Products manufactured have included granular fertilizer, sulfuric acid, super phosphate, and byproduct production of fluorosilic acid. Raw materials include sulfur phosphate rock, potassium salts,

nitrogen as ammonia, ammonium nitrate, and naturally occurring nitrate materials, limestone, inert filler materials, and secondary plant food materials. In the past iron pyrite was roasted on site in the manufacture of sulfuric acid. The use of pyrites was discontinued in the late 1920's (1).

SAMPLING AND ANALYSIS

A number of areas were investigated for this study, including ponds, piles, ditches, an old landfill, and some of the secondary plant food material.

Groundwater samples were collected from a control location, the old acid production (now the acid storage area), the east pond and the landfill. Surface soil samples were collected from all of these areas, and a subsurface soil sample was collected from below the cover of the landfill. Surface water and sediment samples were collected from four ponds on site, and three ditches. Samples were also collected from a former "Base A" storage area ("Base A" is spilled fertilizer material which is blended back into the process), a sulfur pile, and some of the secondary plant food material. All samples were analyzed for total metals and pH, and were evaluated for the possibility of failing the toxicity characteristic leaching procedure (TCLP). Samples containing toxicity characteristic (TC) constituents with concentrations greater than twenty times their regulatory levels were subjected to the TCLP test.

Because of past confusion in interpreting past groundwater data, it should be noted that care was taken to minimize turbidity in the groundwater samples to ensure the highest quality data. To this end, groundwater samples were collected with peristaltic pumps using low flow/low stress procedures.

DISCUSSION OF RESULTS

Previous investigations (1) have shown acid and lead contamination of the groundwater at this facility. The thirty-one samples collected for this investigation confirm the earlier results, and extend the base knowledge of the site. Analytical data is summarized in Tables 1 through 5. Raw data sheets are included in Appendix A.

The data summary tables include the corresponding relevant values from the US-EPA Region III risk-based concentration (RBC) tables, where appropriate. Region III keeps these values current on their web site:

URL http://www.epa.gov./reg3hwmd/risk

The following guidance for use of these RBC's is taken directly from the distribution memo (full text in Appendix B):

"RBCs also have several important limitations. Specifically excluded from consideration are (1) transfers from soil to air and groundwater, and (2) cumulative risk from multiple contaminants or media. Also, the toxicity information in the table has been assembled by hand, and (despite extensive checking and years of use) may contain errors.

Many users want to know if the risk-based concentrations can be used as valid no-action levels or cleanup levels, especially for soils. The answer is a bit complex. First, it is important to realize that the RBC table does not constitute regulation or guidance, and should not be viewed as a substitute for a sitespecific risk assessment. For sites where:

- 1. A single medium is contaminated;
- 2. A single contaminant contributes nearly all of the health risk;
- 3. Volatilization or leaching of that contaminant from soil is expected not to be significant;
- 4. The exposure scenarios used in the RBC table are appropriate for the site;
- 5. The fixed risk levels used in the RBC table are appropriate for the site; and
- 6. Risk to ecological receptors is expected not to be significant;

The risk-based concentrations would probably be protective as no-action levels or cleanup goals. However, to the extent that a site deviates from this description, as most do, the RBCs would not necessarily be appropriate."

"To summarize, the table should generally not be used to (1) set cleanup or no-action levels at CERCLA sites or RCRA Corrective Action sites, (2) substitute for EPA guidance for preparing baseline risk assessments, or (3) determine if a waste is hazardous under RCRA."

These RBC values are included in this report solely to provide a context for the analytical data.

Groundwater Samples - Table 1

No groundwater samples contained TC constituents in concentrations that warranted performing the TCLP. Also, no groundwater samples had pH values of 2 standard units (SU) (or less) or 12.5 (SU) (or greater). However, two samples had low pH values, respectively, SS-013-GW (2.7 SU), collected downgradient of the old acid production area, and SS-016-GW (3.4 SU), collected downgradient of the east pond. As can be seen in Table 1, sample SS-010-GW (control) was the only sample collected that did not exceed Region III RBC screening values for tap water for one or more analytes. Analytes that exceeded the screening values were arsenic, cadmium, lead (no RBC value available, maximum contaminant level (mcl) value exceeded, zinc, aluminum, and manganese.

Soil Samples - Table 2

While TC constituents (lead and arsenic) were found in soil samples, TCLP results showed that none of the samples contained TC metals above their regular levels. Four of the six surface soil samples collected exceeded the Region III RBC value for arsenic (3.8 mg/kg, Table 2). The subsurface soil sample collected from the landfill also contained elevated levels of arsenic, 15 mg/kg. Two surface soil samples contained lead at levels above screening values. The value of 400 mg/kg given as the screening level in Table 2 is the concentration suggested by Region III and is the US-EPA Office of Solid Waste Directive recommended value for residential cleanups.

Surface Water Samples - Table 3

No suitable surface water control locations were noted during the investigation. Most on-site surface water originates from non-contact cooling water generated during the production of sulfuric acid.

No RBC values are yet published for surface water. It should be noted, however, that arsenic was detected in five of the seven surface water samples at concentrations ranging from 11 to 19 ug/l. In addition, lead was detected in four of the seven samples at concentrations ranging from 9.2 to 35 mg/l.

Sediment Samples - Table 4

While TC constituents (arsenic, lead, and antimony) were found in sediment samples, TCLP results showed that none of the samples contained TC metals above their regulated levels.

Also, no sediment samples had pH values of 2 standard units (SU) (or less) or 12.5 (SU) (or greater).

No RBC values are yet published for sediment. A large number of heavy metals were detected in these sediment samples, including arsenic, antimony, barium, cobalt, copper, nickel, lead and mercury. Arsenic was detected in six of the seven samples at concentrations ranging from 13 to 440 mg/kg. Lead was detected in all seven samples at concentrations from 210 to 1400 mg/kg.

Concentrated Media Samples - Table 5

Three samples were collected from various concentrated media at the facility. Analytical results showed that one sample exceeded the TC regulatory level (5 mg/l) for lead. TCLP results of sample SS-008-WA showed it to be a RCRA characteristic D008 waste for lead at 16 mg/l. This solid sample also had a pH of 1.4. This material was described as a waste sulfur pile, but visibly contained significant amounts of other materials. The pile is located on the bank of Holding Pond #1.

Analytical results of sample SS-007-WA showed that it contained 180 mg/kg of mercury. However TCLP results found SS-007-WA to contain 0.007 mg/l which is below the regulatory level of 0.2 mg/l.

CONCLUSIONS

Groundwater Samples - Relative to the control sample (SS-010-GW) it is apparent that releases of contaminants to groundwater have occurred in the acid storage area. In particular, concentrations of arsenic and lead are elevated in this area (along with other heavy metals). While this dataset cannot be definitive, it is possible that the elevated concentrations in the east pond control sample (SS-016-GW) may be due to releases in the acid storage area.

Soil Samples - Again, relative to the control sample (SS-010-SF), it is apparent that releases have occurred in the acid storage area. In particular, lead and arsenic are elevated (along with other heavy metals). Heavy metals were elevated in the other soil samples collected on-site, but not to the degree noted in the acid storage area.

Surface Water and Sediment Samples - No suitable on-site control locations existed for these media, but it is consistent with the groundwater and soil samples that arsenic and lead were

detected in these samples. Arsenic and lead are being released off-site to surface water and sediment via the ditch at the discharge end of pond #2. This study did not determine if this release is partially due to on-going activities, or solely to historical releases.

Concentrated Media - The soil sample collected from the former base "A" storage area contained elevated arsenic and lead (and other heavy metals) relative to the control soil sample (SS-010-SF). No suitable control exists for the No. 12 material. The analytical results for this sample (SS-007-WA) showed high levels of several heavy metals (lead, mercury, copper, mercury, etc.), but did not contain TC constituents above regulated levels. The sample collected from the sulfur pile (SS-008-WA) did contain lead above regulated levels (16 mg/kg in the TCLP extract).

ME THODOLOGY

Groundwater samples were not collected from existing permanent wells, but were collected from temporary shallow well points. All samples were collected and handled in accordance with the US-EPA, Region IV, Science and Ecosystem Services Division, Environmental Investigations Standard Operating Procedures and Quality Assurance Manual (EISOPQAM), May, 1996. The samples were analyzed in accordance with the Analytical Support Branch Laboratory Operations and Quality Control Manual, September, 1990.

References

(1) Southern States Phosphate & Fertilizer Co., Environmental Assessment & Remediation Plan, April 24, 1992.






FIGURE 1
SITE LOCATION MAP
SOUTHERN STATES PHOSPHATE & FERTILIZER CO.
SAVANNAH, GEORGIA

NOT TO SCALE

TABLE 1
ANALYTICA' RESULTS
GROUNDWA' SAMPLES GROUNDWA' SAMPLES SOUTHERN TATES DIE NOVEMBER 4-6, 1996

	REGION3 RBC VALUE TAP WATER	SS010GW CONTROL WELL 11/05/96 1535	SS012GW ACID CONTROL 11/05/96 1825	SS013GW ACID DOWNGRAD 11/05/96 2000	SS016GW EASTPOND CONTROL 11/06/96 1140	SS014GW EASTPOND DOWNGRAD 11/06/96 1620	SS017GW LANDFILL DOWNGRAD 11/06/96 1415
INORGANIC ELEMENTS	UG/L	UG/L	UG/L	UG/L	UG/L	UG/L	ug/L
ARSENIC BARIUM CADMIUM COBALT CHROMIUM COPPER MOLYBDENUM NICKEL LEAD STRONTIUM TITANIUM VANADIUM ZINC MERCURY ALUMINUM MANGANESE	0.045 2600 18 2200 180N* 1500 180 730 15* 22000 ** 260 11000 11 37000 840	120 	15 49 17 30 18 26 64 160 120 14 53 0.57 1400 58	160 230 12 160 26 210 870 2000 3200 35 840 1.2 34000 940	200 57 180 95 280 390 27 1600 72 230 11000 75000 43000	 11 98 60 26 500 930 1700 4300	51
	MG/L	MG/L	MG/L	MG/L	MG/L	MG/L	
CALCIUM MAGNESIUM IRON SODIUM POTASSIUM	11000 **	4.8 0.36 0.30 2.6	59 10 1.4 160 9.1	220 20 32 440 41	590 190 20 84 340	110 16 9.4 110 110	390 130 180 350 340
TCLP	**	NA	ИИ	АИ	АИ	АИ	АИ
SPECIFIED ANALYSIS	SU	SU	SU	SU	SU	SU	SU
рН	+ *	4.9	6.0	2.7	3.4	6.0A	4.5

 $^{^\}star$ - The value given is for chromiumVI, the value given for lead is the MCL ** - No published RBC value NA - Not Analyzed

TABLE 2 ANALYTICA RESULTS SOIL S LES SOUTHERN SLATES DIE NOVEMBER 4-6, 1996

	REGION 3 RBC VALUE INDUSTRY SOIL	SS010SF CONTROL WELL 11/05/96 1350	SS012SF ACID CONTROL 11/05/96 1530	SS013SF ACID DOWNGRAD 11/05/96 1615	SS016SF EASTPOND CONTROL 11/06/96 0900	SS014SF EASTPOND DOWNGRAD 11/06/96 1005	SS017SF LANDFILL DOWNGRAD 11/06/96 1240	SS015SB CENTER LANDFILL 11/06/96 1330
INORGANIC ELEMENTS	MG/KG	MG/KG	MG/KG	MG/KG	MG/KG	MG/KG	MG/KG	MG/KG
ARSENIC BARIUM CADMIUM COBALT CHROMIUM COPPER MOLYBDENUM NICKEL LEAD ANTIMONY TIN STRONTIUM TITANIUM VANADIUM YTTRIUM ZINC MERCURY ALUMINUM MANGANESE CALCIUM MAGNESIUM IRON SODIUM POTASSIUM	3.8 140000 1000 120000 1000000 82000 10000 41000 41000 400* 820 10000000 ** 610000 610 1000000 47000 **	2.0 8.5 3.8 19 30 3.4 60 2.6 1.0 6.9 3800 5.7 100 120 1300	13 200 8.4 30 490 890 140 74 0.12 3600 110 94000 17000 7200 840 	110 2400 14 260 10 2400 41 49 88 190 0.32 930 39 2000 440 72000 	2.7 68 1.2 9.9 28 2.7 75 67 460 12 12 61 0.11 4900 80 12000 840 7000 390 1900	23 120 150 190 31 78 160 26 76 92 150 21 64 0.34 1300 400 36000 250 100000	33 77 16 74 100 68 72 130 130 17 470 0.14 64000 380 4300 4100 60000 1200 6800	15 99 3.9 10 41 140 4.2 18 150 47 26 490 0.20 25000 180 34000 34000 32000 350 2800
TCLP	MG/L	MG/L	MG/L	MG/L	MG/L	MG/L	MG/L	MG/L
ARSENIC LEAD	NA NA	NA NA	0.45	1.2	NA NA		0.059	0.61
SPECIFIED ANALYSIS	SU	su	SU	SU	SU	SU	SU	SU
рĦ	NA	4.6	7.0	5.9	3.4A	2.5	5.4	5.6

^{***}FOOTNOTES***

The value given for lead is from the EPA Office of Solid Waste directive for residential soil.
 NA - Not Analyzed

TABLE 3 ANALYTICAL RESULTS SURFACE WATER SAMPLES SOUTHERN STATES DIE NOVEMBER 4-6, 1996

	SS001SW HOLDING POND #2 11/05/96 1038	SS002SW BLDG DITCH 11/04/96 1620	SS003SW HOLDING POND #1 11/04/96 1705	SS004SW SCALES DITCH 11/04/96 1655	SS005SW ACID PLANT 11/05/96 1130	SS009SW WEST POND 11/05/96 1330	SS011SW EAST POND 11/05/96 1410
INORGANIC ELEMENTS	UG/L	UG/L	UG/L	UG/L	UG/L	UG/L	UG/L
ARSENIC BARIUM COBALT COPPER NICKEL LEAD STRONTIUM ZINC MERCURY ALUMINUM MANGANESE	12 14 12 9.22 110	16 11 320 44 23	19 20 18 35 35 54 54 6.21 840 44	23 24 25 - 25 - 25 - 2 - 2	12 13 9.2 400	11 24 280 140 310 230	8.0 17 110 44 770 2600 0.21 1800 4900
	MG/L	MG/L	MG/L	MG/L	MG/L	MG/L	MG/L
CALCIUM MAGNESIUM IRON SODIUM POTASSIUM	25 9.0 0.34 23	25 8.2 10 10	29 8.8 1.4 19 2.1	30 8.2 0.48 12 2.0	24 8.8 0.24 18	60 12 0.12 16 40	110 15 0.15 130 120
TCLP	NA	NA	NA	NA.	AN	NA	AN
S .IFIED ANALYSIS	su	su	SU	SU	SU	SU	SU
рН	7.9	7.8	7.6	7.5	8.2A	7.8	5.7

FOOTNOTES

NA - Not Analyzed

TABLE 4
ANALYTICAL RESULTS
SEDIMENT SAMPLES
SCUTHERN STATES DIE
NOVEMBER 4-6, 1996

	SS001SD HOLDING POND #2 11/05/96 1050	SS002SD BLDG DITCH 11/04/96 1625	SS003SD HOLDING POND #1 11/04/96 1710	SS004SD SCALES DITCH 11/04/96 1700	SS005SD ACID PLANT 11/05/96 1135	SS009SD WEST POND 11/05/96 1350	SS011SD EAST POND 11/05/96 1420
INORGANIC ELEMENTS	MG/KG	MG/KG	MG/KG	MG/KG	MG/KG	MG/KG	
ARSENIC BARIUM CADMIUM COBALT CHROMIUM COPPER NICKEL LEAD ANTIMONY TIN STRONTIUM TITANIUM VANADIUM YTTRIUM ZINC MERCURY ALUMINUM MANGANESE CALCIUM MAGNESIUM IRON SODIUM POTASSIUM	46 670 7.7 69 700 25 15 840 200 7.3 110 1.5 190 89 4400 13000	24 730 10 56 450 880 280 130 1800 800 850 2800 18000 3500	440 690 8.6 100 110 140 140 140 140 140 140	13 220 33 360 210 2600 140 48 74 1700 0.06 8400 1400 0.2500 11000 3000 	29 320 66 420 2800 430 190 0.36 4300 290 210000 29000 14000 12000	29 320 15 82 820 50 380 1100 620 1300 0.47 34000 14000 21000 24000 2900	14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
TCLP	MG/L	MG/L	MG/L	MG/L	MG/L	MG/L	MG/L
ARSENIC LEAD ANTIMONY	0.23 2.2 0.28	0.54	0.18 0.39	 	 0.1€	0.077 	
SPECIFIED ANALYSIS	SU	SU	SU	su	SU	SU	su
рн '	7.5	6.6	9.7	6.9A	11	7.1	4.8A
FOOTNOTES	*****	*******	*****	•			

NA - Not Analyzed

TABLE 5 ANALYTICAL RESULTS CONCENTRATED SAMPLES SOUTHERN STATES DIE NOVEMBER 4-6, 1996


	ייתיי שמקם	NO. 12	SS008WA SULFUR PILE 11/05/96 1155
INORGANIC ELEMENTS	MG/KG	MG/KG	MG/KG
BERYLLIUM CADMIUM COBALT CHECMIUM COPPER NICKEL LEAD TIN STRONTIUM TITANIUM VANADIUM YTTRIUM ZINC MERCURY DIMMINIM	22 250 24 100 1600 34 220 49 1200 140 22 5800 1.3 4600 12000 9000 2300 7100	76 1400 37 53 27000 4600 1500 5200 110 8400 13000 31000 31000 327000 14000	11 24 3.1 26 4.3 1200 81 38 40 0.40 340 49 7400 3000 2290
TCLP	MG/L	MG/L	MG/L
CADMIUM LEAL MERCURY		0.54 0.12 0.007	16
SPECIFIED ANALYSIS	SU	su	su
pH ;	6.9	9.2A	1.4
FOOTNCTES *********************************	****	*******	*******

NA - Not Analyzed

APPENDIX A

page 5 of 7

from 9/12/88 GAEPD Trip Report



「さん・オエ∠∠ンじ4み30

ייין פל טו חשר איז א איז איז פל טו חשר Jun 10 '99 04:25PM

HUNTER, MACLEAN, EXLEY & DUNN, P.C.

ATTORNEYS AT LAW

Savannam Office:
Post Office Box 9848
Savannam, Georgià 31412-0048
Telephone: (912) 236-0261
Facsimile: (912) 236-4936
or (912) 232-8653

200 East Saint Julian Street Savannah, Georgia 31401

> ANDREW H. ERNST SAVANNAH OFFICE

ATLANTA OFFICE:
1355 PEACHTREE STREET, N.E.
SUITE 640
ATLANTA, GEORGIA 30309
TELEPHONE: (404) 876-3611
FACSIMILE: (404) 870-2025

June 10, 1999

⊍ **(999**

VIA FACSIMILE (404) 651-9425

Ms. Ann Roat
Hazardous Waste Management Branch
Georgia Department of Natural Resources
205 Butler Street, S.E.
Suite 1154
Atlanta, GA 30334

FILE COPY

RE: Proposed Consent Order, Southern States Phosphate and Fertilizer Company

Dear Ms. Roat:

Per our discussion last week, enclosed you will find a copy of the Exhibit which was sent to me by Mr. Compton at Southern States. This Exhibit identifies two piles of pyrite located at the facility.

As you and I discussed, the order was a little ambiguous as to the location of materials to be removed. I will use this Exhibit in an effort to more clearly define those sites needing removal.

I hope to have revised consent order for your consideration within the next few days. With best regards, I am


Very truly yours,

Andrew H. Ernst

AHE/aha Enclosure

cc: Mr. Keith Compton

(244513-1) 5681-5



PRESIDEN I S

SOUTHERN STATES
PROSPRATE & FERTILIZER CO.

DATE: FEBRUARY 7, 1994

SCALE: 1"- 200"

.

(15GW-1) SOUTHERN STATES 0000000 FACILITY 00 00 00 APIARY-Ø IND. CHEMICALS 0 0 SPOIL DISPOSAL AREA

PRESIDENT STREET EXTENTION

JORDAN SIGN COMPANY SITE

GADOO3293057

(SITE SKETCH)

I" = 400'

From 9/12/88 GA EPD Trip Report

